



WBA11DX080CE10350

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	171,932 km
Manufacturer	BMW	Next maintenance in	24,000 km
Type / Model	520d	Main inspection (Report on hand)	01/2027
Vehicle Identification number	WBA11DX080CE10350	Power / Engine displacement	140 kW / 1,995 ccm
First registration	17 Feb 2020	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Hybrid Diesel / E	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - rear right side - Scratched - No deduction
2	Sill - left side	Sill - Dent / paintcoat damage - Smart repair
3	Interior	Cargo area floor - Soiled - Clean
4	Instrument panel	Centre console - front - Scratched - Replace
5	Sill - right side	Trim - Scratched - Repair and paint
6	Door - rear right side	Door - Scratched - Repair and paint
7	Vehicle glazing	Windscreen - Stone chips - Replace
8	Rear bumper	Rear bumper - Scratched - Repair and paint
9	Side panel - rear right side	Side panel - Deformed - Repair and paint
10	Front bumper	Front bumper - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Body	Body - Scratch(es) - No deduction
2	Interior	Interior - Abrasion - No deduction

Missing parts

Missing part

Previous damages

No.	Previous damage
1	Front, Provided by user / customer

Detected repainting

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 18 Mar 2025
Protocol number: 38906526
Delivery date: 18 Mar 2025



Auto Plus

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/55 R17 101V	Michelin	Summer tyres	7mm - 7mm	o.k.	
2	225/55 R17 101V	Michelin	Summer tyres	6mm - 6mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/55 R17 101Y	Goodyear	Summer tyres	7mm - 7mm	o.k.	
2	225/55 R17 101Y	Goodyear	Summer tyres	5mm - 5mm	o.k.	

Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					10/2025

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 18 Mar 2025
Protocol number: 38906526
Delivery date: 18 Mar 2025



Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	520d	Mileage (Read)	171,932 km
Vehicle Identification number	WBA11DX080CE10350	First registration	17 Feb 2020

Vehicle identification:

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior




Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior




Figure 10: Misc.



Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 22: Misc.

Pictures of damage



Damage #1: Wheel / tyres: Alloy rim - rear right side - Scratched - No deduction



Damage #1: Wheel / tyres: Alloy rim - rear right side - Scratched - No deduction



Damage #2: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage #2: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage #3: Interior: Cargo area floor - Soiled - Clean



Damage #3: Interior: Cargo area floor - Soiled - Clean



Damage #4: Instrument panel: Centre console - front - Scratched - Replace



Damage #4: Instrument panel: Centre console - front - Scratched - Replace



Damage #5: Sill - right side: Trim - Scratched - Repair and paint



Damage #5: Sill - right side: Trim - Scratched - Repair and paint



Damage #6: Door - rear right side: Door - Scratched - Repair and paint



Damage #6: Door - rear right side: Door - Scratched - Repair and paint



Damage #7: Vehicle glazing: Windscreen - Stone chips - Replace



Damage #7: Vehicle glazing: Windscreen - Stone chips - Replace



Damage #7: Vehicle glazing: Windscreen - Stone chips - Replace



Damage #8: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #8: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #8: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #8: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #8: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #9: Side panel - rear right side: Side panel - Deformed - Repair and paint



Damage #9: Side panel - rear right side: Side panel - Deform... - Repair and paint



Damage #9: Side panel - rear right side: Side panel - Deformed - Repair and paint



Damage #10: Front bumper: Front bumper - Broken / torn - Replace

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 18 Mar 2025
Protocol number: 38906526
Delivery date: 18 Mar 2025



Damage #10: Front bumper: Front bumper - Broken / torn - Replace



Damage #10: Front bumper: Front bumper - Broken / torn - Replace



Damage #10: Front bumper: Front bumper - Broken / torn - Replace