



Brand:	BMW	Mileage(km):	149401
Model:	740	Number of doors:	4
Model type:	740i Org.NL Leder Trekhaak	Vehicle length (cm):	
License plate:	HV043X	Vehicle width (cm):	
Report code:	4961	Vehicle height (cm):	
Chassis number:	WBA7A21070GD34961	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Rear
First int. reg.:	11/01/2016	Power(kw):	240
First NL req.:	11/01/2016	Transmission:	Automatic
Color:	Blue <input checked="" type="checkbox"/> Metallic	Number of gears:	8
Weight (kg)(kg):	1800	Displacement(cc):	2998
Empty weight(kg):	1700	Number of cylinders:	6
Wheelbase (cm)(cm):	307	Fuel type:	Petrol
Top speed (km/h):	250	Fuel tank capacity:	
Cons. in the city (l/100 km):	9.4	EU category:	Euro 6
Cons. outside the city (l/100 km):	5.3	Energy label:	C
Average consumption (l/100 km):	6.8	NL Tax Rate %:	25
Acceleration (s):	5.5	CO2 (g/km):	159
Cargo space (l):	1800	Nb. of Axles:	2
Perm. max weight (kg):	2400	APK date:	02/03/2026

opties

- Alloy wheels
- Leather upholstery
- Air suspension
- Digital dashboard
- Daytime running lights
- Licht Sensor
- Towing hook
- Anti-lock braking system
- ABS
- Airbag(s)
- Audio
- Central locking system
- Fog lamps
- Start/stop system
- Power steering
- Front seats adjustable in height
- Multifunctional steering wheel
- Remote central locking
- Metallic finish
- LED headlights
- LED rear lights
- Exterior mirrors in car body color
- Exterior mirrors with step light
- Privacy glass
- Rain sensor
- Rear view camera
- Rear parking sensors
- Front parking sensors
- Towbar with retractable ball
- Rear-seat folding (equal parts)
- Rear-seat folding (unequal parts)
- Ski hatch
- Luggage cover
- Trunk opens electrically
- USB connection
- Bluetooth streaming
- CD changer
- Radio/cassette player
- Bluetooth car kit
- Radio
- Cruise control
- Airconditioning
- Airconditioning in the back
- Climate control
- Climate control (analog)
- Climate control (digital)
- Climate control (L/R separated)
- Large screen navigation
- Keyless entry
- Keyless entry/start/stop
- Keyless start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Electrically adjustable driver's seat
- Electrically adjustable driver's seat (including memory)
- Electrically adjustable passenger seat
- Electrically adjustable passenger seat (including memory)
- Electrically heated driver's seat
- Electrically heated passenger seat
- Central armrest front
- Audio control on the steering wheel
- Electrically adjustable steering wheel
- Leather steering wheel

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Alloy	245/45 R19	Continental	7
Tire left rear	All weather	Alloy	245/45 R19	Continental	7
Tire right front	All weather	Alloy	245/45 R19	Continental	7
Tire right rear	All weather	Alloy	245/45 R19	Continental	7

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Brown	Maintenance booklet:	(door universeel)	<input checked="" type="checkbox"/> Odorless
Upholstery:	Leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	16/01/2017	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	33396	<input checked="" type="checkbox"/> Vehicle special usage (None)

⚠ Cleaning

- Clean inside (Interior is clean)
- Clean outside (Polishing)

🔧 Damages

⊕ Not acceptable



Front right rim - Scratch



Front bumper - Scratch




Grille - Break



Front left rim - Scratch



Rear left rim - Scratch



Rear bumper - Scratch



Rear bumper - Scratch



Rear right screen - Paint repair



Rear right rim - Scratch



Right C- column - Restyle dent

🔧 Damages

⊕ Acceptable

⚙ Extra options



