



WAUZZZFZ5RP054743

Vehicle details

Operator		Inspection condition	conditional: sufficient
License number		Mileage (Read)	13,081 km
Manufacturer	Audi	Next maintenance in	12 Monat(e)
Type / Model	Q4 45 e-tron	Main inspection (Read from ZBI)	04/2027
Vehicle Identification number	WAUZZZFZ5RP054743	Power / Engine displacement	89 kW
First registration	4 Apr 2024	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Electric	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	2nd wheel set	2 tyres (Sommer / ohne Notlaufeigenschaft) - Replace
2	Wheel / tyres	Tyre - front (Winter / ohne Notlaufeigenschaft) - Replace
3	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Body	Body - Stone chips - No deduction
2	Body	Body - Scratch(es) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Interior	Interior - Abrasion - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	235/55 R19 101H	Pirelli	Winter tyres	7mm - 7mm	o.k.	
2	255/50 R19 103T	Pirelli	winter tires (with run-flat tires)	6mm - 6mm	o.k.	

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 19 Mar 2025
Protocol number: 38918057
Delivery date: 19 Mar 2025



Auto Plus

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	235/55 R19 101T	Hankook	Summer tyres	5mm - 5mm	o.k.	
2	255/50 R19 103T	Bridgestone	summer tires (with run-flat tires)	5mm - 5mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 19 Mar 2025
Protocol number: 38918057
Delivery date: 19 Mar 2025



Auto Plus

Vehicle details

Manufacturer	Audi	Inspection condition	conditional: sufficient
Type / Model	Q4 45 e-tron	Mileage (Read)	13,081 km
Vehicle Identification number	WAUZZZFZ5RP054743	First registration	4 Apr 2024

Vehicle identification:

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

Inspection conditions:

The inspection conditions were only partially sufficient for assessing the vehicle. At the time of the inspection, it could not be ensured that the condition was sufficient for an adequate assessment. The expert therefore recommends a further inspection to reduce the risk of prognosis.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior




Figure 10: Misc.



Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.




Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 19 Mar 2025
Protocol number: 38918057
Delivery date: 19 Mar 2025



Auto Plus

Pictures of damage



Damage #3: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage #3: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint