



WAUZZZF44RA010448

## Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	31,377 km
Manufacturer	Audi	Next maintenance in	-1,300 km
Type / Model	A4 Limousine	Main inspection (Read from ZBI)	10/2026
Vehicle Identification number	WAUZZZF44RA010448	Power / Engine displacement	110 kW / 1,984 ccm
First registration	31 Oct 2023	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Hybrid Petrol / E	Gearbox	Automatic

## Zustandsbericht

### Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - front left side - Scratched - Loss in value
2	Misc.	Inspection / maintenance - Due - Replace

### Wear and tear

No.	Component group	Description
1	Body	Body - Stone chips - No deduction
2	Body	Body - Scratch(es) - No deduction
3	Interior	Interior - Abrasion - No deduction
4	Vehicle glazing	Windscreen - Stone chips - No deduction

### Missing parts

Missing part

### Detected repainting

No.	Location
1	Door - front right side, Professionally carried out

### Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	205/60 R16 96H	Goodyear	Winter tyres	6mm - 6mm	o.k.	
2	205/60 R16 96H	Goodyear	Winter tyres	7mm - 7mm	o.k.	

**TÜV SÜD Auto Plus GmbH**  
Gutenbergstr. 13  
70771 Leinfelden-Echterdingen

**Inspection location**  
Allane Mobility Consulting  
GmbH

69190 Walldorf

Inspection date: 18 Mar 2025

**Protocol number:** 38937246

Delivery date: 18 Mar 2025



Auto Plus

## Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	205/60 R16 92H	Michelin	Summer tyres	6mm - 6mm	o.k.	
2	205/60 R16 92H	Michelin	Summer tyres	6mm - 6mm	o.k.	

## Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					07/2027

The wear and tear condition and possible damages to the tyres are considered in the value.

## Comments

Keine Gewähr auf Vollständigkeit und

Richtigkeit der angezeigten Ausstattung.

Techn. Änderungen vorbehalten

Das Fahrzeug weist dem Alter, der Laufleistung und dem  
Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, n .i. O.

**TÜV SÜD Auto Plus GmbH**  
Gutenbergstr. 13  
70771 Leinfelden-Echterdingen

**Inspection location**  
Allane Mobility Consulting  
GmbH  
69190 Walldorf

Inspection date: 18 Mar 2025  
**Protocol number: 38937246**  
Delivery date: 18 Mar 2025



---

## Vehicle details

<b>Manufacturer</b>	Audi	<b>Inspection condition</b>	Sufficient
<b>Type / Model</b>	A4 Limousine	<b>Mileage (Read)</b>	31,377 km
<b>Vehicle Identification number</b>	WAUZZZF44RA010448	<b>First registration</b>	31 Oct 2023

**Vehicle identification:**

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

**Inspection conditions:**

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

**General condition:**

The vehicle shows traces of wear and tear corresponding to its age and purpose

## Overview pictures



**Figure 1:** Diagonal front



**Figure 2:** Diagonal front




**Figure 3:** Diagonal rear



**Figure 4:** Diagonal rear



**Figure 5:** Interior



**Figure 6:** Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.




Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.

**TÜV SÜD Auto Plus GmbH**  
Gutenbergstr. 13  
70771 Leinfelden-Echterdingen

**Inspection location**  
Allane Mobility Consulting  
GmbH

69190 Walldorf

Inspection date: 18 Mar 2025  
**Protocol number: 38937246**  
Delivery date: 18 Mar 2025



## Pictures of damage



**Damage #1:** Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



**Damage #1:** Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



**Damage #2:** Misc.: Inspection / maintenance - Due - Replace