



WAUZZZFY4L2125782

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	124,719 km
Manufacturer	Audi	Next maintenance in	12,900 km
Type / Model	Q5 50 TFSI e	Main inspection (Report on hand)	12/2025
Vehicle Identification number	WAUZZZFY4L2125782	Power / Engine displacement	185 kW / 1,984 ccm
First registration	15 Jan 2021	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Hybr.B/E ext. edition	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Front bumper	Front bumper - Scratch(es) - Cover / polish
2	Trim / covers	Floor mats - Damaged - Replace
3	Trim / covers	Boot lid - interior trim - Scratched - Loss in value
4	Door - front left side	Door - dent(s) - Smooth repair work
5	Roof	Roof rail - right side - dent(s) - Smooth repair work
6	2nd wheel set	1 alloy rim - Scratched - Loss in value
7	Side panel - rear left side	Sill - Scratched - Smart repair
8	Side panel - rear right side	Wheel well extension - Scratched - Smart repair
9	Vehicle glazing	Windscreen with rain sensor - Damaged - Replace
10	Trim / covers	Carpet - front left side - Damaged - Replace
11	Rear bumper	Rear bumper - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Door - front left side	Door edge - Scratched - No deduction
2	Body	Body - Stone chips - No deduction
3	Interior	Interior - Abrasion - No deduction

Missing parts

Missing part

Previous damages

No.	Previous damage
1	Front, Provided by user / customer

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 6 Mar 2025

Protocol number: 38771120

Delivery date: 6 Mar 2025



Auto Plus

Detected repainting

No.	Location
1	Bumper front, Professionally carried out

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	235/65 R17 104H	Dunlop	Winter tyres	5mm - 5mm	o.k.	
2	235/65 R17 108H	Michelin	Winter tyres	7mm - 7mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	235/55 R19 105Y	Goodyear	Summer tyres	4mm - 4mm	o.k.	
2	235/55 R19 105Y	Goodyear	Summer tyres	5mm - 5mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, n .i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 6 Mar 2025

Protocol number: 38771120

Delivery date: 6 Mar 2025



Auto Plus

Vehicle details

Manufacturer	Audi	Inspection condition	Sufficient
Type / Model	Q5 50 TFSI e	Mileage (Read)	124,719 km
Vehicle Identification number	WAUZZZFY4L2125782	First registration	15 Jan 2021

Vehicle identification:

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.



Figure 12: Misc.




Figure 13: Misc.



Figure 14: Misc.




Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.





Figure 21: Misc.




Figure 22: Misc.


Pictures of damage



Damage #1: Front bumper: Front bumper - Scratch(es) - Cover / polish



Damage #1: Front bumper: Front bumper - Scratch(es) - Cover / polish



Damage #2: Trim / covers: Floor mats - Damaged - Replace



Damage #2: Trim / covers: Floor mats - Damaged - Replace



Damage #3: Trim / covers: Boot lid - interior trim - Scratched - Loss in value



Damage #3: Trim / covers: Boot lid - interior trim - Scratched - Loss in value



Damage #4: Door - front left side: Door - dent(s) - Smooth repair work




Damage #4: Door - front left side: Door - dent(s) - Smooth repair work



Damage #5: Roof: Roof rail - right side - dent(s) - Smooth repair work



Damage #5: Roof: Roof rail - right side - dent(s) - Smooth repair work



Damage #5: Roof: Roof rail - right side - dent(s) - Smooth repair work




Damage #6: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage #6: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage #7: Side panel - rear left side: Sill - Scratched - Smart repair




Damage #7: Side panel - rear left side: Sill - Scratched - Smart repair



Damage #7: Side panel - rear left side: Sill - Scratched - Smart repair



Damage #8: Side panel - rear right side: Wheel well extension - Scratched - Smart repair




Damage #8: Side panel - rear right side: Wheel well extension - Scratched - Smart repair



Damage #8: Side panel - rear right side: Wheel well extension - Scratched - Smart repair



Damage #9: Vehicle glazing: Windscreen with rain sensor - Damaged - Replace



Damage #10: Trim / covers: Carpet - front left side - Damaged - Replace



Damage #9: Vehicle glazing: Windscreen with rain sensor - Damaged - Replace



Damage #10: Trim / covers: Carpet - front left side - Damage... Replace



Damage #11: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage #11: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #11: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #11: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #11: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #11: Rear bumper: Rear bumper - Scratched - Repair and paint