



WBA5P51050FK86760

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	85,118 km
Manufacturer	BMW	Next maintenance in	410 km
Type / Model	330e	Main inspection (Report on hand)	02/2026
Vehicle Identification number	WBA5P51050FK86760	Power / Engine displacement	135 kW / 1,998 ccm
First registration	3 Feb 2021	Upholstery/Colour	/
Last maintenance	02/2024, 61,930 km	Paintwork	
Fuel type	Hybr.B/E ext. edition	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Tyres - complete set - Expired - No deduction
2	Wheel / tyres	Alloy rim - front left side - Scratched - No deduction
3	Wheel / tyres	Alloy rim - front right side - Scratched - No deduction
4	Wheel / tyres	Alloy rim - rear right side - Scratched - No deduction
5	Side panel - rear left side	Side panel - Scratch(es) - Cover / polish
6	2nd wheel set	1 alloy rim - Scratched - Loss in value
7	Misc.	Inspection / maintenance - Due - Replace
8	Vehicle glazing	Windscreen - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Interior	Interior - Abrasion - No deduction
2	Body	Body (Steinschläge) - Scratch(es) - No deduction
3	Door - front right side	Door edge - Scratched - No deduction

Missing parts

Missing part

Previous damages

No.	Previous damage
1	Front, Provided by user / customer

Detected repainting

No.	Location
	None detectable

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 11 Mar 2025

Protocol number: 38790550

Delivery date: 11 Mar 2025



Auto Plus

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/45 R18 95V	Pirelli	Winter tyres	3mm - 3mm	Not o.k.	
2	225/45 R18 95V	Pirelli	Winter tyres	2mm - 2mm	Not o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/45 R18 95Y	Dunlop	Summer tyres	7mm - 7mm	o.k.	
2	255/40 R18 99Y	Bridgestone	Summer tyres	3mm - 3mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und

Richtigkeit der angezeigten Ausstattung.

Techn. Änderungen vorbehalten

Das Fahrzeug weist dem Alter, der Laufleistung und dem

Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

Fahrzeug war zum Zeitpunkt der Besichtigung regennass, weitere Beschädigungen können nicht ausgeschlossen werden

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 11 Mar 2025

Protocol number: 38790550

Delivery date: 11 Mar 2025



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	conditional: light/moisture/dirt
Type / Model	330e	Mileage (Read)	85,118 km
Vehicle Identification number	WBA5P51050FK86760	First registration	3 Feb 2021

Vehicle identification:

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

Inspection conditions:

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear




Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior




Figure 9: Interior




Figure 10: Misc.



Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.




Figure 18: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 11 Mar 2025
Protocol number: 38790550
Delivery date: 11 Mar 2025



Auto Plus




Figure 19: Misc.

Pictures of damage



Damage #2: Wheel / tyres: Alloy rim - front left side - Scratched - No deduction




Damage #2: Wheel / tyres: Alloy rim - front left side - Scratched - No deduction




Damage #3: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction



Damage #3: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction



Damage #4: Wheel / tyres: Alloy rim - rear right side - Scratched - No deduction



Damage #4: Wheel / tyres: Alloy rim - rear right side - Scratched - No deduction



Damage #5: Side panel - rear left side: Side panel - Scratch(es) - Cover / polish



Damage #6: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage #5: Side panel - rear left side: Side panel - Scratch(es) - Cover / polish



Damage #8: Vehicle glazing: Windscreen - Stone chips - Replace