



WAUZZZF55PA019486

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	49,867 km
Manufacturer	Audi	Next maintenance in	8,200 km
Type / Model	A5 Sportback	Main inspection (Read from ZBI)	11/2025
Vehicle Identification number	WAUZZZF55PA019486	Power / Engine displacement	150 kW / 1,968 ccm
First registration	23 Nov 2022	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Hybrid Diesel / E	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratched - Cover / polish
2	Wing mirror - right side	Cap - Scratched - Smart repair
3	Front bumper	Front bumper - Scratched - Smart repair
4	Vehicle glazing	Windscreen - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Body	Body - Scratch(es) - No deduction
2	Interior	Interior - Abrasion - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
1	Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98H	Pirelli	Winter tyres	5mm - 5mm	o.k.	
2	225/50 R17 98H	Pirelli	Winter tyres	6mm - 6mm	o.k.	

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 31 Mar 2025

Protocol number: 39097450

Delivery date: 31 Mar 2025



Auto Plus

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 94H	Pirelli	Summer tyres	5mm - 5mm	o.k.	
2	225/50 R17 94H	Pirelli	Summer tyres	6mm - 6mm	o.k.	

Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					09/2026

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und

Richtigkeit der angezeigten Ausstattung.

Techn. Änderungen vorbehalten

Das Fahrzeug weist dem Alter, der Laufleistung und dem

Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, N.i.O

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 31 Mar 2025

Protocol number: 39097450

Delivery date: 31 Mar 2025



Auto Plus

Vehicle details

Manufacturer	Audi	Inspection condition	Sufficient
Type / Model	A5 Sportback	Mileage (Read)	49,867 km
Vehicle Identification number	WAUZZZF55PA019486	First registration	23 Nov 2022

Vehicle identification:

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 31 Mar 2025

Protocol number: 39097450

Delivery date: 31 Mar 2025



Auto Plus



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 31 Mar 2025
Protocol number: 39097450
Delivery date: 31 Mar 2025



Auto Plus



Figure 19: Misc.



Figure 20: Misc.

Pictures of damage



Damage #1: Rear bumper: Rear bumper - Scratched - Cover / polish



Damage #1: Rear bumper: Rear bumper - Scratched - Cover / polish



Damage #2: Wing mirror - right side: Cap - Scratched - Smart repair



Damage #2: Wing mirror - right side: Cap - Scratched - Smart repair



Damage #3: Front bumper: Front bumper - Scratched - Smart repair




Damage #3: Front bumper: Front bumper - Scratched - Smart repair



Damage #3: Front bumper: Front bumper - Scratched - Smart repair




Damage #4: Vehicle glazing: Windscreen - Stone chips - Replace



Damage #4: Vehicle glazing: Windscreen - Stone chips - Replace



Damage #4: Vehicle glazing: Windscreen - Stone chips - Replace



Damage #4: Vehicle glazing: Windscreen - Stone chips - Replace