



WBA31BN070CG90391

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	44,629 km
Manufacturer	BMW	Next maintenance in	0 Monat(e)
Type / Model	520d	Main inspection (Report on hand)	05/2026
Vehicle Identification number	WBA31BN070CG90391	Power / Engine displacement	140 kW / 1,995 ccm
First registration	30 Mar 2021	Upholstery/Colour	/
Last maintenance	05/2024, 35,755 km	Paintwork	
Fuel type	Hybrid Diesel / E	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	2nd wheel set	1 alloy rim - Scratched - Loss in value
2	Boot lid / rear door	Rear spoiler - Scratched - Smart repair
3	Misc.	Inspection / maintenance - Due - Replace
4	Door - rear right side	Door - Scratch(es) - Repair and paint
5	Rear bumper	Rear bumper - Scratched - Repair and paint
6	Front bumper	Front bumper - Scratched - Repair and paint
7	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint
8	Bonnet	Bonnet - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Body	Body (Steinschläge) - Scratch(es) - No deduction
2	Vehicle glazing	Windscreen (Steinschläge) - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
1	Door - front left side

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/55 R17 97H	Pirelli	Winter tyres	7mm - 7mm	o.k.	
2	225/55 R17 97H	Pirelli	Winter tyres	6mm - 6mm	o.k.	

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 28 Mar 2025
Protocol number: 39078421
Delivery date: 28 Mar 2025



Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/55 R17 101Y	Hankook	Summer tyres	6mm - 6mm	o.k.	
2	225/55 R17 101Y	Hankook	Summer tyres	5mm - 5mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, N.i.O

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 28 Mar 2025

Protocol number: 39078421

Delivery date: 28 Mar 2025



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	520d	Mileage (Read)	44,629 km
Vehicle Identification number	WBA31BN070CG90391	First registration	30 Mar 2021

Vehicle identification:

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 28 Mar 2025
Protocol number: 39078421
Delivery date: 28 Mar 2025



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior




Figure 10: Misc.



Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.


Pictures of damage



Damage #1: 2nd wheel set: 1 alloy rim - Scratched - Loss in value




Damage #2: Boot lid / rear door: Rear spoiler - Scratched - Smart repair



Damage #4: Door - rear right side: Door - Scratch(es) - Repair and paint



Damage #4: Door - rear right side: Door - Scratch(es) - Repair and paint




Damage #5: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #5: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #5: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage #6: Front bumper: Front bumper - Scratched - Repair and paint



Damage #6: Front bumper: Front bumper - Scratched - Repair and paint



Damage #6: Front bumper: Front bumper - Scratched - Repair and paint



Damage #6: Front bumper: Front bumper - Scratched - Repair and paint




Damage #6: Front bumper: Front bumper - Scratched - Repair and paint




Damage #7: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint




Damage #7: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage #7: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage #8: Bonnet: Bonnet - Scratched - Repair and paint



Damage #8: Bonnet: Bonnet - Scratched - Repair and paint