



WBA11CG040CG79830

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	72,437 km
Manufacturer	BMW	Next maintenance in	25,000 km
Type / Model	530e	Main inspection (Report not on hand)	04/2026
Vehicle Identification number	WBA11CG040CG79830	Power / Engine displacement	135 kW / 1,998 ccm
First registration	15 Mar 2021	Upholstery/Colour	/
Last maintenance	09/2024, 63,464 km	Paintwork	
Fuel type	Hybr.B/E ext. edition	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Boot lid / rear door	Boot lid - Scratch(es) - Cover / polish
2	Side panel - rear left side	Interior trim - Scratched - Loss in value
3	Documents	Main inspection certificate (Fehlt) - Replace
4	Door - rear left side	Door handle - outside - Scratched - Smart repair
5	Fuel system	Tank cap - Scratched - Smart repair
6	Mudguard - left side	Mudguard - left side - Scratched - Smart repair
7	Rear bumper	Rear bumper - Scratched - Smart repair
8	Side panel - rear left side	Sill - Scratched - Smart repair
9	Sill - right side	Trim - Scratched - Repair and paint
10	Front bumper	Front bumper - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Interior	Interior - Abrasion - No deduction
2	Body	Body (Steinschläge) - Scratch(es) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 24 Mar 2025
Protocol number: 38981817
Delivery date: 24 Mar 2025



Auto Plus

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	245/45 R18 100V	Pirelli	Winter tyres	7mm - 7mm	o.k.	
2	245/45 R18 100V	Pirelli	Winter tyres	6mm - 6mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	245/45 R18 100Y	Pirelli	Summer tyres	7mm - 7mm	o.k.	
2	245/45 R18 100Y	Pirelli	Summer tyres	6mm - 6mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

Fahrzeug war zum Zeitpunkt der Besichtigung verschmutzt, weitere Beschädigungen können nicht ausgeschlossen werden

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 24 Mar 2025
Protocol number: 38981817
Delivery date: 24 Mar 2025



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	conditional: light/moisture/dirt
Type / Model	530e	Mileage (Read)	72,437 km
Vehicle Identification number	WBA11CG040CG79830	First registration	15 Mar 2021

Vehicle identification:

The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.

Inspection conditions:

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures




Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior




Figure 9: Interior



Figure 10: Misc.




Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.




Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 24 Mar 2025
Protocol number: 38981817
Delivery date: 24 Mar 2025



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.


Pictures of damage



Damage #1: Boot lid / rear door: Boot lid - Scratch(es) - Cover / polish



Damage #1: Boot lid / rear door: Boot lid - Scratch(es) - Cove...
polish




Damage #2: Side panel - rear left side: Interior trim - Scratched -
Loss in value



Damage #4: Door - rear left side: Door handle - outside -
Scratched - Smart repair



Damage #4: Door - rear left side: Door handle - outside - Scratch...
- Smart repair



Damage #5: Fuel system: Tank cap - Scratched - Smart repair



Damage #6: Mudguard - left side: Mudguard - left side - Scratched - Smart repair



Damage #6: Mudguard - left side: Mudguard - left side - Scratched - Smart repair




Damage #7: Rear bumper: Rear bumper - Scratched - Smart repair



Damage #7: Rear bumper: Rear bumper - Scratched - Smart repair



Damage #8: Side panel - rear left side: Sill - Scratched - Smart repair



Damage #8: Side panel - rear left side: Sill - Scratched - Smart repair




Damage #8: Side panel - rear left side: Sill - Scratched - Smart repair



Damage #9: Sill - right side: Trim - Scratched - Repair and paint



Damage #9: Sill - right side: Trim - Scratched - Repair and paint



Damage #10: Front bumper: Front bumper - Scratched - Rep... and paint



Damage #10: Front bumper: Front bumper - Scratched - Repair and paint



Damage #10: Front bumper: Front bumper - Scratched - Rep... and paint

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 24 Mar 2025
Protocol number: 38981817
Delivery date: 24 Mar 2025



Auto Plus



Damage #10: Front bumper: Front bumper - Scratched - Repair and paint



Damage #10: Front bumper: Front bumper - Scratched - Rep... and paint