



Brand:	Land Rover	Mileage(km):	130239
Model:	Range Rover Sport	Number of doors:	5
Model type:	3.0 SDV6 Autobiography Dynamic	Vehicle length (cm):	
License plate:	HV727R	Vehicle width (cm):	
Report code:	0385	Vehicle height (cm):	
Chassis number:	SALWA2KF3GA630385	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front+Rear
First int. reg.:	05/01/2016	Power(kw):	225
First NL req.:	05/01/2016	Transmission	Automatic
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears	8
Weight (kg)(kg):	2203	Displacement(cc):	2993
Empty weight(kg):	2103	Number of cylinders:	6
Wheelbase (cm)(cm):	292	Fuel type:	Diesel
Top speed (km/h):	225	Fuel tank capacity:	
Cons. in the city (l/100 km):	7.9	EU category:	Euro 6
Cons. outside the city (l/100 km):	6.4	Energy label:	E
Average consumption (l/100 km):	7	NL Tax Rate %:	25
Acceleration (s):	7.2	CO2 (g/km):	185
Cargo space (l):	2203	Nb. of Axles:	2
Perm. max weight (kg):	3050	APK date:	22/03/2026

opties

<input checked="" type="checkbox"/> Alloy wheels	<input checked="" type="checkbox"/> Xenon headlights (adaptive)	<input checked="" type="checkbox"/> Keyless start/stop
<input checked="" type="checkbox"/> Leather upholstery	<input checked="" type="checkbox"/> Headlight washers	<input checked="" type="checkbox"/> Electrically operated rear windows
<input checked="" type="checkbox"/> Air suspension	<input checked="" type="checkbox"/> LED rear lights	<input checked="" type="checkbox"/> Electrically operated front windows
<input checked="" type="checkbox"/> Digital dashboard	<input checked="" type="checkbox"/> Exterior mirrors in car body color	<input checked="" type="checkbox"/> Electrically heated windscreen
<input checked="" type="checkbox"/> Daytime running lights	<input checked="" type="checkbox"/> Rain sensor	<input checked="" type="checkbox"/> Electrically folding mirrors
<input checked="" type="checkbox"/> Licht Sensor	<input checked="" type="checkbox"/> Rear wiper	<input checked="" type="checkbox"/> Electrically adjustable mirrors
<input checked="" type="checkbox"/> bots waarschuwing systeem	<input checked="" type="checkbox"/> Rear view camera	<input checked="" type="checkbox"/> Electrically adjustable driver's seat
<input checked="" type="checkbox"/> Anti-lock braking system	<input checked="" type="checkbox"/> Rear parking sensors	<input checked="" type="checkbox"/> Electrically adjustable driver's seat (including memory)
<input checked="" type="checkbox"/> ABS	<input checked="" type="checkbox"/> Front parking sensors	<input checked="" type="checkbox"/> Electrically adjustable passenger seat
<input checked="" type="checkbox"/> Airbag(s)	<input checked="" type="checkbox"/> Luggage cover	<input checked="" type="checkbox"/> Electrically adjustable passenger seat (including memory)
<input checked="" type="checkbox"/> Audio	<input checked="" type="checkbox"/> Trunk opens electrically	<input checked="" type="checkbox"/> Electrically heated driver's seat
<input checked="" type="checkbox"/> bots herkenning systeem	<input checked="" type="checkbox"/> USB connection	<input checked="" type="checkbox"/> Electrically heated passenger seat
<input checked="" type="checkbox"/> Central locking system	<input checked="" type="checkbox"/> Bluetooth car kit	<input checked="" type="checkbox"/> Central armrest front
<input checked="" type="checkbox"/> Fog lamps	<input checked="" type="checkbox"/> Cruise control	<input checked="" type="checkbox"/> Adjustable lumbar support driver's seat
<input checked="" type="checkbox"/> Start/stop system	<input checked="" type="checkbox"/> Head-up Display	<input checked="" type="checkbox"/> Adjustable lumbar support passenger seat
<input checked="" type="checkbox"/> Stoelverwarming-Koeling	<input checked="" type="checkbox"/> Black top interior	<input checked="" type="checkbox"/> Audio control on the steering wheel
<input checked="" type="checkbox"/> Power steering	<input checked="" type="checkbox"/> Airconditioning	<input checked="" type="checkbox"/> Electrically adjustable steering wheel
<input checked="" type="checkbox"/> Front seats adjustable in height	<input checked="" type="checkbox"/> Airconditioning in the back	<input checked="" type="checkbox"/> Leather steering wheel
<input checked="" type="checkbox"/> Multifunctional steering wheel	<input checked="" type="checkbox"/> Climate control	<input checked="" type="checkbox"/> Switch flippers
<input checked="" type="checkbox"/> Remote central locking	<input checked="" type="checkbox"/> Climate control (digital)	<input checked="" type="checkbox"/> Heated steering wheel
<input checked="" type="checkbox"/> Sports package (exterior)	<input checked="" type="checkbox"/> Climate control (L/R separated)	<input checked="" type="checkbox"/> Lane assistance
<input checked="" type="checkbox"/> Metallic finish	<input checked="" type="checkbox"/> Large screen navigation	<input checked="" type="checkbox"/> Pedestrian safety system
<input checked="" type="checkbox"/> Panoramic roof (electrical)	<input checked="" type="checkbox"/> Keyless entry	<input checked="" type="checkbox"/> Dead angle assistance
<input checked="" type="checkbox"/> Xenon headlights	<input checked="" type="checkbox"/> Keyless entry/start/stop	

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	275/40 R22	Continental	7
Tire left rear	Winter	Alloy	275/40 R22	Continental	7
Tire right front	Winter	Alloy	275/40 R22	Continental	7
Tire right rear	Winter	Alloy	275/40 R22	Continental	7

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Beige	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	11/06/2020	<input checked="" type="checkbox"/> Display ok

No. of headrests:

5

Last turn mileage(km):

66907

☒ Vehicle special usage (None)

⚠ Cleaning

☒ Clean inside (Interior is clean)

☐ Clean outside

🔧 Damages

⊕ Not acceptable



Rear left rim - Scratch



Front right rim - Scratch



Front bumper - Weatherworn



Front bumper - Scratch



Rear bumper - Rust formation



Rear bumper - Scratch



Right outside mirror - Scratch



Breuk in het instrumentenpaneel

🔧 Damages

⊕ Acceptable

⚙ Extra options





