



Brand:	Jaguar	Mileage(km):
Model:	XE	Number of doors:
Model type:	2.0 Aut. D Portfolio   Leder   Camera	Vehicle length (cm):
License plate:	PN789J	Vehicle width (cm):
Report code:	1329	Vehicle height (cm):
Chassis number:	SAJAB4BN8HCP01329	Vehicle body type:
Type of vehicle:	Luxury	Traction:
First int. reg.:	03/08/2017	Power(kw):
First NL reg.:	03/08/2017	Transmission
Color:	Grey 🔽 Metallic	Number of gears
Weight (kg)(kg):	1565	Displacement(cc):
Empty weight(kg):	1465	Number of cylinders:
Wheelbase (cm)(cm):	284	Fuel type:
Top speed (km/h):	227	Fuel tank capacity:
Cons. in the city (I/100 km):	5	EU category:
Cons. outside the city (I/100 km):	3.5	Energy label:
Avarage consumption (I/100 km):	4.1	NL Tax Rate %:
Acceleration (s):	8.2	CO2 (g/km):
Cargo space (I):	1565	Nb. of Axles:
Perm. max weight (kg):	2100	APK date:

Vehicle length (cm):	
Vehicle width (cm):	
Vehicle height (cm):	
Vehicle body type:	
Traction:	Rear
Power(kw):	120
Transmission	Automatic
Number of gears	8
Displacement(cc):	1999
Number of cylinders:	4
Fuel type:	Diesel
Fuel tank capacity:	
EU category:	Euro 6
Energy label:	С

Inspected by: Mik Kieft

125759 4

106 2 18/08/2025

#### 🚓 opties

_	
<ul> <li>Image: A set of the set of the</li></ul>	Alloy wheels
~	Leather upholstery
~	Daytime running lights
	Licht Sensor
	bots waarschuwing systeem
~	Anti-lock braking system
~	ABS
~	Anti-lock braking system Anti-lock braking system ABS Airbag(s) Audio bots herkenning system Central locking system Start/stop system Power steering Front seats adjustable in height Multifunctional steering wheel Remote central locking
~	Audio
~	bots herkenning systeem
~	Central locking system
~	Start/stop system
~	Power steering
~	Front seats adjustable in height
~	Multifunctional steering wheel
~	Remote central locking
~	Metallic finish
-	Xenon headlights

	Xenon headlights (adaptive)
$\mathbf{\mathbf{Z}}$	5 ( 1 )
$\mathbf{}$	Headlight washers
$\checkmark$	LED rear lights
222	Exterior mirrors in car body color
$\checkmark$	Rain sensor
<u>388888888888888888</u>	Rear view camera
	Rear parking sensors
$\checkmark$	Front parking sensors
$\checkmark$	USB connection
	Radio/CD player
	Bluetooth car kit
	WiFi
$\overline{}$	Cruise control
~	Airconditioning
$\overline{}$	Airconditioning in the back
$\overline{}$	Climate control
~	Climate control (digital)
	Climate control (L/R separated)

_	
$\sim$	Large screen navigation
$\checkmark$	Keyless entry
<ul> <li></li> </ul>	Keyless entry/start/stop
~	Keyless start/stop
$\overline{}$	Electrically operated rear windows
$\overline{}$	Electrically operated front windows
~	Electrically folding mirrors
<	Electrically adjustable mirrors
	Electrically heated driver's seat
১১১১	Electrically heated passenger seat
	Central armrest front
	Adjustable lumbar support driver's seat
~	Adjustable lumbar support passenger seat
	Audio control on the steering wheel
<	Leather steering wheel
~	Switch flippers
	Lane assistance
<ul> <li></li> </ul>	Pedestrian safety system

## 📽 Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	205/55 R17	Pirelli	6
Tire left rear	Summer	Alloy	205/55 R17	Pirelli	6
Tire right front	Summer	Alloy	205/55 R17	Pirelli	6
Tire right rear	Summer	Alloy	205/55 R17	Pirelli	6

#### Additional information No. of keys: 2 Luxury key Instruction booklet Airco works Interior color: Maintenance booklet: Odorless Upholstery: Leder Clean inside (Interior is clean) No. of seats: 5 Stamp date: Display ok No. of headrests: Last turn mileage(km): Vehicle special usage (None)

Clean outside (Polishing)

## 🔎 Damages

# Not acceptable



Front bumper - Scratch



Left sill - Scratch



Front left door - Restyle dent




Right sill - Scratch



Front left door - Scratch

ℱ Damages	Acceptable	
📽 Extra options		






























































## AUTOF CTOR software for automotive