



Brand:	Fiat	Mileage(km):	125434
Model:	500	Number of doors:	3
Model type:	0.9 TwinAir Turbo Popstar	Vehicle length (cm):	
License plate:	NJ662K	Vehicle width (cm):	
Report code:	5974	Vehicle height (cm):	
Chassis number:	ZFA3120000J675974	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	20/02/2017	Power(kw):	59
First NL req.:	20/02/2017	Transmission	Manual
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears	5
Weight (kg)(kg):	1005	Displacement(cc):	875
Empty weight(kg):	905	Number of cylinders:	2
Wheelbase (cm)(cm):	230	Fuel type:	Petrol
Top speed (km/h):	171	Fuel tank capacity:	
Cons. in the city (l/100 km):	4.5	EU category:	Euro 6
Cons. outside the city (l/100 km):	3.4	Energy label:	A
Average consumption (l/100 km):	3.8	NL Tax Rate %:	
Acceleration (s):	11	CO2 (g/km):	88
Cargo space (l):	1005	Nb. of Axles:	2
Perm. max weight (kg):	1370	APK date:	20/02/2026

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Radio/CD player |
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Radio/CD/MP3 player |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Halogen headlights | <input checked="" type="checkbox"/> Radio |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Climate control |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Rear-seat folding (equal parts) | <input checked="" type="checkbox"/> Climate control (analog) |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Start/stop system | <input checked="" type="checkbox"/> Aux connection | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> iPod connection | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> USB connection | |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> Bluetooth streaming | |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	185/55 R15	Continental	5
Tire left rear	Summer	Alloy	185/55 R15	Continental	5
Tire right front	Summer	Alloy	185/55 R15	Continental	5
Tire right rear	Summer	Alloy	185/55 R15	Continental	5

Additional information

No. of keys:	1	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:		<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	4	Stamp date:		<input checked="" type="checkbox"/> Display ok
No. of headrests:	4	Last turn mileage(km):		<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Polishing)


6 Damages



Front left rim - Scratch



Front right rim - Scratch



Front left screen - Restyle dent



Rear bumper - Scratch



Rear right screen - Dent



Front left door - Restyle dent



Roof - Bird droppings



Windscreen - Pip






Left B- column - Restyle dent

Damages

Ⓢ Acceptable

Extra options







AUTOF[▲]CTOR
SOFTWARE FOR AUTOMOTIVE