



WBA6Y310007F30916

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	78,448 km
Manufacturer	BMW	Next maintenance in	16,000 km
Type / Model	225xe iPerformance	Main inspection (Report on hand)	12/2026
Vehicle Identification number	WBA6Y310007F30916	Power / Engine displacement	100 kW / 1,499 ccm
First registration	3 Dec 2019	Upholstery/Colour	/
Last maintenance	12/2024, 74,708 km	Paintwork	
Fuel type	Hybr.B/E ext. edition	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	2nd wheel set	1 alloy rim - Scratched - Loss in value
2	Electrical system	Switch (Fest) - Specify findings - Perform diagnosis
3	Front bumper	Spoiler - Scratched - Replace
4	Mudguard - left side	Mudguard - left side - Dent / paintcoat damage - Repair and paint
5	Rear bumper	Rear bumper - Scratched - Repair and paint
6	Door - rear left side	Door - Dent / paintcoat damage - Repair and paint
7	Bonnet	Bonnet - Scratched - Paint
8	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint
9	Front bumper	Front bumper - Scratched - Replace

Wear and tear

No.	Component group	Description
1	Interior	Interior - Abrasion - No deduction
2	Body	Body (Steinschläge) - Scratch(es) - No deduction
3	Vehicle glazing	Windscreen (Steinschläge) - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
	None detectable

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 9 Apr 2025

Protocol number: 39254630

Delivery date: 9 Apr 2025



Auto Plus

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	205/55 R17 95H	Pirelli	Winter tyres	4mm - 4mm	o.k.	
2	205/55 R17 95H	Pirelli	Winter tyres	5mm - 5mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	205/55 R17 95W	Bridgestone	Summer tyres	3mm - 3mm	o.k.	
2	205/55 R17 95V	Pirelli	Summer tyres	6mm - 6mm	o.k.	

Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					10/2025

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 9 Apr 2025
Protocol number: 39254630
Delivery date: 9 Apr 2025



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	225xe iPerformance	Mileage (Read)	78,448 km
Vehicle Identification number	WBA6Y310007F30916	First registration	3 Dec 2019

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear




Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior




Figure 10: Misc.



Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 9 Apr 2025
Protocol number: 39254630
Delivery date: 9 Apr 2025



Auto Plus



Figure 25: Misc.



Figure 26: Misc.

Pictures of damage



Damage #1: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage #1: 2nd wheel set: 1 alloy rim - Scratched - Loss in value




Damage #2: Electrical system: Switch (Fest) - Specify findings - Perform diagnosis




Damage #3: Front bumper: Spoiler - Scratched - Replace




Damage #3: Front bumper: Spoiler - Scratched - Replace




Damage #4: Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Repair and paint



Damage #4: Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Repair and paint




Damage #4: Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Repair and paint




Damage #5: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage #5: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage #6: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint




Damage #6: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint




Damage #6: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint




Damage #7: Bonnet: Bonnet - Scratched - Paint




Damage #7: Bonnet: Bonnet - Scratched - Paint



Damage #8: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage #8: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage #8: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage #9: Front bumper: Front bumper - Scratched - Replace



Damage #9: Front bumper: Front bumper - Scratched - Replace



Damage #9: Front bumper: Front bumper - Scratched - Replace



Damage #9: Front bumper: Front bumper - Scratched - Replace