



WAUZZZF28MN074749

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	69,548 km
Manufacturer	Audi	Next maintenance in	23 Tag(e)
Type / Model	A6 Avant	Main inspection (Report on hand)	04/2026
Vehicle Identification number	WAUZZZF28MN074749	Power / Engine displacement	150 kW / 1,968 ccm
First registration	9 Apr 2021	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Hybrid Diesel / E	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Side panel - rear left side	Side panel - Scratch(es) - Cover / polish
2	Misc.	Inspection / maintenance - Due - Replace
3	Roof	Roof rail - right side - Paint defect - Repair and paint
4	Rear bumper	Rear bumper - Scratched - Repair and paint
5	Front bumper	Front bumper - Scratched - Repair and paint
6	Side panel - rear right side	Side panel - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Wing mirror - right side	Cap (Steinschläge) - No deduction
2	Body	Body (Steinschläge) - Scratch(es) - No deduction
3	Interior	Interior - Abrasion - No deduction
4	Vehicle glazing	Windscreen (Steinschläge) - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/60 R17 103V	Dunlop	Winter tyres	6mm - 6mm	o.k.	
2	225/60 R17 103H	Michelin	Winter tyres	8mm - 8mm	o.k.	

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 8 Apr 2025
Protocol number: 39217793
Delivery date: 8 Apr 2025



Auto Plus

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/55 R18 102V	Michelin	Summer tyres	3mm - 3mm	o.k.	
2	225/55 R18 102V	Michelin	Summer tyres	6mm - 6mm	o.k.	

Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					05/2026

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 8 Apr 2025
Protocol number: 39217793
Delivery date: 8 Apr 2025



Vehicle details

Manufacturer	Audi	Inspection condition	Sufficient
Type / Model	A6 Avant	Mileage (Read)	69,548 km
Vehicle Identification number	WAUZZZF28MN074749	First registration	9 Apr 2021

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior




Figure 10: Misc.




Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.

Pictures of damage



Damage #1: Side panel - rear left side: Side panel - Scratch(es) - Cover / polish



Damage #1: Side panel - rear left side: Side panel - Scratch(es) - Cover / polish




Damage #2: Misc.: Inspection / maintenance - Due - Replace



Damage #3: Roof: Roof rail - right side - Paint defect - Repair and paint



Damage #3: Roof: Roof rail - right side - Paint defect - Repair and paint




Damage #4: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #4: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #4: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage #5: Front bumper: Front bumper - Scratched - Repair and paint



Damage #5: Front bumper: Front bumper - Scratched - Repair and paint



Damage #5: Front bumper: Front bumper - Scratched - Repair and paint



Damage #6: Side panel - rear right side: Side panel - Scratch... - Repair and paint

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 8 Apr 2025
Protocol number: 39217793
Delivery date: 8 Apr 2025



Auto Plus



Damage #6: Side panel - rear right side: Side panel - Scratched -
Repair and paint