



WAUZZZF49MA009692

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	76,098 km
Manufacturer	Audi	Next maintenance in	14,200 km
Type / Model	A4 40 TFSI S tronic quattro Avant Kombi5-türig	Main inspection	
Vehicle Identification number	WAUZZZF49MA009692	Power / Engine displacement	/ 1,984 ccm
First registration	5 Oct 2020	Upholstery/Colour	Cloth / Red-Black
Last maintenance		Paintwork	Black
Fuel type	Petrol	Gearbox	

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - rear right side - Scratched - No deduction
2	Wheel / tyres	Tyre - rear right side - Damaged - No deduction
3	Door - rear right side	Door - dent(s) - Smooth repair work
4	Rear bumper	Spoiler - Abrasion - Replace
5	2nd wheel set	1 tyre - Damaged - Replace
6	Rear bumper	Rear bumper - Dent / paintcoat damage - Repair and paint
7	Vehicle glazing	Windscreen with rain sensor - Damaged - Replace
8	2nd wheel set	1 alloy rim - Scratched - Replace

Wear and tear

No.	Component group	Description
The vehicle shows traces of wear and tear corresponding to its age and purpose		

Missing parts

Missing part

Previous damages

No.	Previous damage
1	Side - left, Provided by user / customer, from 24 Apr 2022
2	Rear, Side right, Provided by user / customer, from 10 Aug 2023

Detected repainting



No.	Location
1	Door - front left side, Professionally carried out, Invoice of repair done Non-existent

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	205/60 R16 96H	Dunlop	Winter tyres	5mm - 5mm	o.k.	o.k.
2	205/60 R16 96H	Dunlop	Winter tyres	5mm - 5mm	o.k.	o.k.

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 94H	Continental	Summer tyres	4mm - 4mm	o.k.	o.k.
2	225/50 R17 94H	Continental	Summer tyres	5mm - 5mm	o.k.	o.k.

The wear and tear condition and possible damages to the tyres are considered in the value.

Equipment

Equipment

Description
Automatic air conditioning
Navigation unit with map view
Radio DAB

Comments

Für die Richtig- und Vollständigkeit der Basisdaten - wird keine Gewähr übernommen!

Ausstattungsliste nicht verfügbar.

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten.
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, n. i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 16 Apr 2025
Protocol number: 39477871



Auto Plus

Vehicle details

Manufacturer	Audi	Inspection condition	conditional: light/moisture/dirt
Type / Model	A4 40 TFSI S tronic quattro Avant Kombi5-türig	Mileage (Read)	76,098 km
Vehicle Identification number	WAUZZZF49MA009692	First registration	5 Oct 2020

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior




Figure 7: Interior



Figure 8: Interior




Figure 9: Interior



Figure 10: Interior



Figure 11: Interior



Figure 12: Interior



Figure 13: VIN



Figure 14: Accessories




Figure 15: Documents



Figure 16: Mounted tyres



Figure 17: Misc.



Figure 18: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 16 Apr 2025
Protocol number: 39477871



Figure 19: Misc.



Figure 20: Misc.


Pictures of damage




Damage #1: Wheel / tyres: Alloy rim - rear right side - Scratched - No deduction



Damage #2: Wheel / tyres: Tyre - rear right side - Damaged - No deduction



Damage #3: Door - rear right side: Door - dent(s) - Smooth repair work



Damage #3: Door - rear right side: Door - dent(s) - Smooth repair work



Damage #4: Rear bumper: Spoiler - Abrasion - Replace



Damage #5: 2nd wheel set: 1 tyre - Damaged - Replace



Damage #5: 2nd wheel set: 1 tyre - Damaged - Replace




Damage #6: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage #6: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage #6: Rear bumper: Rear bumper - Dent / paintcoat damage - Repair and paint



Damage #7: Vehicle glazing: Windscreen with rain sensor - Damaged - Replace



Damage #7: Vehicle glazing: Windscreen with rain sensor - Damaged - Replace

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 16 Apr 2025
Protocol number: 39477871



Auto Plus



Damage #7: Vehicle glazing: Windscreen with rain sensor - Damaged - Replace



Damage #8: 2nd wheel set: 1 alloy rim - Scratched - Replace

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen


Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 16 Apr 2025
Protocol number: 39477871



Auto Plus

Pictures of repainting



Repainting 1: Door - front left side