



WAUZZZF29MN074372

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	89,744 km
Manufacturer	Audi	Next maintenance in	20 Tag(e)
Type / Model	A6 50 TFSI e	Main inspection (Report on hand)	05/2026
Vehicle Identification number	WAUZZZF29MN074372	Power / Engine displacement	195 kW / 1,984 ccm
First registration	1 Apr 2021	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Hybr.B/E ext. edition	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Documents	Service book (Wartungsnachweise fehlen) - No deduction
2	Wheel / tyres	Alloy rim - front right side - Scratched - No deduction
3	Wheel / tyres	Alloy rim - rear right side - Scratched - No deduction
4	Seat - front	Backrest cover - left side - Abrasion - Loss in value
5	2nd wheel set	2 alloy rims - Scratched - Loss in value
6	Front bumper	Front bumper - Scratched - Smart repair
7	Misc.	Inspection / maintenance - Due - Replace
8	Door - rear right side	Door - Scratch(es) - Repair and paint

Wear and tear

No.	Component group	Description
1	Interior	Interior - Abrasion - No deduction
2	Body	Body (Steinschläge) - Scratch(es) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 7 Apr 2025

Protocol number: 39197616

Delivery date: 7 Apr 2025



Auto Plus

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	245/45 R19 102V	Michelin	Winter tyres	5mm - 5mm	o.k.	
2	245/45 R19 102V	Michelin	Winter tyres	5mm - 5mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	255/40 R20 101Y	Pirelli	Summer tyres	7mm - 7mm	o.k.	
2	255/40 R20 101Y	Pirelli	Summer tyres	7mm - 7mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und

Richtigkeit der angezeigten Ausstattung.

Techn. Änderungen vorbehalten

Das Fahrzeug weist dem Alter, der Laufleistung und dem

Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 7 Apr 2025
Protocol number: 39197616
Delivery date: 7 Apr 2025



Vehicle details

Manufacturer	Audi	Inspection condition	Sufficient
Type / Model	A6 50 TFSI e	Mileage (Read)	89,744 km
Vehicle Identification number	WAUZZZF29MN074372	First registration	1 Apr 2021

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior




Figure 9: Interior



Figure 10: Misc.




Figure 11: Misc.




Figure 12: Misc.




Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 7 Apr 2025
Protocol number: 39197616
Delivery date: 7 Apr 2025



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.


Pictures of damage



Damage #2: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction




Damage #2: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction




Damage #3: Wheel / tyres: Alloy rim - rear right side - Scratched - No deduction



Damage #3: Wheel / tyres: Alloy rim - rear right side - Scratched - No deduction



Damage #4: Seat - front: Backrest cover - left side - Abrasion - Loss in value




Damage #4: Seat - front: Backrest cover - left side - Abrasion - Loss in value



Damage #5: 2nd wheel set: 2 alloy rims - Scratched - Loss in value



Damage #5: 2nd wheel set: 2 alloy rims - Scratched - Loss in value



Damage #6: Front bumper: Front bumper - Scratched - Smart repair



Damage #6: Front bumper: Front bumper - Scratched - Smart repair



Damage #6: Front bumper: Front bumper - Scratched - Smart repair



Damage #8: Door - rear right side: Door - Scratch(es) - Repair and paint

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen


Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 7 Apr 2025
Protocol number: 39197616
Delivery date: 7 Apr 2025



Auto Plus



Damage #8: Door - rear right side: Door - Scratch(es) - Repair and paint