



WAUZZZGY7MA086496

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	127,457 km
Manufacturer	Audi	Next maintenance in	11,700 km
Type / Model	A3 40 TFSIe	Main inspection (Report on hand)	03/2026
Vehicle Identification number	WAUZZZGY7MA086496	Power / Engine displacement	110 kW / 1,395 ccm
First registration	1 Apr 2021	Upholstery/Colour	/
Last maintenance	02/2025, 66,806 km	Paintwork	
Fuel type	Hybr.B/E ext. edition	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - front left side - Scratched - No deduction
2	Seat - front	Seat cover - left side - Scratched - Loss in value
3	Front bumper	Front bumper - Paint defect - Loss in value
4	2nd wheel set	1 alloy rim - Scratched - Loss in value
5	Door - rear left side	Door - Scratched - Smart repair

Wear and tear

No.	Component group	Description
1	Rear bumper	Rear bumper - Abrasion - No deduction
2	Door - rear right side	Door edge - Stone chips - No deduction
3	Body	Body (Steinschläge) - Scratch(es) - No deduction
4	Interior	Interior - Abrasion - No deduction
5	Vehicle glazing	Windscreen (Steinschläge) - No deduction

Missing parts

Missing part

Previous damages

No.	Previous damage
1	Front, Provided by user / customer

Detected repainting

No.	Location
	None detectable

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP Deutschland SE & Co.
KG
Hasso-Plattner-Ring 7
69190 Walldorf

Inspection date: 10 Apr 2025
Protocol number: 39280685
Delivery date: 10 Apr 2025



Auto Plus

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	205/55 R16 91T	Goodyear	Winter tyres	6mm - 6mm	o.k.	
2	205/55 R16 91T	Goodyear	Winter tyres	8mm - 8mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/40 R18 92Y	Pirelli	Summer tyres	4mm - 4mm	o.k.	
2	225/40 R18 92Y	Pirelli	Summer tyres	6mm - 6mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP Deutschland SE & Co.
KG
Hasso-Plattner-Ring 7
69190 Walldorf

Inspection date: 10 Apr 2025
Protocol number: 39280685
Delivery date: 10 Apr 2025



Auto Plus

Vehicle details

Manufacturer	Audi	Inspection condition	Sufficient
Type / Model	A3 40 TFSIe	Mileage (Read)	127,457 km
Vehicle Identification number	WAUZZZGY7MA086496	First registration	1 Apr 2021

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP Deutschland SE & Co.
KG
Hasso-Plattner-Ring 7
69190 Walldorf

Inspection date: 10 Apr 2025
Protocol number: 39280685
Delivery date: 10 Apr 2025



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.




Figure 11: Misc.




Figure 12: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP Deutschland SE & Co.
KG
Hasso-Plattner-Ring 7
69190 Walldorf

Inspection date: 10 Apr 2025
Protocol number: 39280685
Delivery date: 10 Apr 2025




Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP Deutschland SE & Co.
KG
Hasso-Plattner-Ring 7
69190 Walldorf

Inspection date: 10 Apr 2025
Protocol number: 39280685
Delivery date: 10 Apr 2025



Figure 25: Misc.




Figure 26: Misc.

Pictures of damage



Damage #1: Wheel / tyres: Alloy rim - front left side - Scratched - No deduction



Damage #1: Wheel / tyres: Alloy rim - front left side - Scratched - No deduction




Damage #2: Seat - front: Seat cover - left side - Scratched - Loss in value



Damage #2: Seat - front: Seat cover - left side - Scratched - Loss in value



Damage #3: Front bumper: Front bumper - Paint defect - Loss in value



Damage #3: Front bumper: Front bumper - Paint defect - Loss in value




Damage #3: Front bumper: Front bumper - Paint defect - Loss in value




Damage #4: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage #4: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage #5: Door - rear left side: Door - Scratched - Smart repair



Damage #5: Door - rear left side: Door - Scratched - Smart repair