



Brand:	Ford	Mileage(km):	158736
Model:	Fiesta	Number of doors:	5
Model type:	1.0 EcoBoost Hybrid Titanium LED	Vehicle length (cm):	
License plate:	P863KV	Vehicle width (cm):	
Report code:	8151	Vehicle height (cm):	
Chassis number:	WF0JXXGAHJNY08151	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	13/04/2022	Power(kw):	92
First NL req.:	13/04/2022	Transmission	Manual
Color:	White <input type="checkbox"/> Metallic	Number of gears	6
Weight (kg)(kg):	1211	Displacement(cc):	999
Empty weight(kg):	1111	Number of cylinders:	3
Wheelbase (cm)(cm):	249	Fuel type:	Petrol
Top speed (km/h):	203	Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	B
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):	9.4	CO2 (g/km):	1
Cargo space (l):	1211	Nb. of Axles:	2
Perm. max weight (kg):	1690	APK date:	13/04/2026

## opties

- |  |  |   |
|--|--|---|
| <input checked="" type="checkbox"/> Daytime running lights           | <input checked="" type="checkbox"/> LED rear lights                    | <input checked="" type="checkbox"/> Airconditioning                     |
| <input checked="" type="checkbox"/> Licht Sensor                     | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Climate control                     |
| <input checked="" type="checkbox"/> Anti-lock braking system         | <input checked="" type="checkbox"/> Rain sensor                        | <input checked="" type="checkbox"/> Climate control (digital)           |
| <input checked="" type="checkbox"/> ABS                              | <input checked="" type="checkbox"/> Rear wiper                         | <input checked="" type="checkbox"/> Large screen navigation             |
| <input checked="" type="checkbox"/> Airbag(s)                        | <input checked="" type="checkbox"/> Rear parking sensors               | <input checked="" type="checkbox"/> Electrically operated rear windows  |
| <input checked="" type="checkbox"/> Audio                            | <input checked="" type="checkbox"/> Luggage cover                      | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Central locking system           | <input checked="" type="checkbox"/> USB connection                     | <input checked="" type="checkbox"/> Electrically adjustable mirrors     |
| <input checked="" type="checkbox"/> Power steering                   | <input checked="" type="checkbox"/> DAB+                               | <input checked="" type="checkbox"/> Central armrest front               |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Bluetooth car kit                  | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Multifunctional steering wheel   | <input checked="" type="checkbox"/> Radio                              | <input checked="" type="checkbox"/> Leather steering wheel              |
| <input checked="" type="checkbox"/> Remote central locking           | <input checked="" type="checkbox"/> WiFi                               | <input checked="" type="checkbox"/> Lane assistance                     |
| <input checked="" type="checkbox"/> LED headlights                   | <input checked="" type="checkbox"/> Cruise control                     |   |

## Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Steel	195/60 R15	Goodyear	6
Tire left rear	All weather	Steel	195/60 R15	Goodyear	6
Tire right front	All weather	Steel	195/60 R15	Goodyear	6
Tire right rear	All weather	Steel	195/60 R15	Goodyear	6

## Additional information

No. of keys:	1	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	22/05/2024	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	140621	<input checked="" type="checkbox"/> Vehicle special usage (None)

## Cleaning

- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

## 6. Damages



Rear left screen - Dent



Rear bumper - Dent

### 🔧 Damages

⊕ Acceptable

### ⚙️ Extra options



