



WAUZZZF47MA003146

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	54,233 km
Manufacturer	Audi	Next maintenance in	5,800 km
Type / Model	A4 Avant	Main inspection (Report on hand)	07/2025
Vehicle Identification number	WAUZZZF47MA003146	Power / Engine displacement	140 kW / 1,968 ccm
First registration	21 Aug 2020	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Diesel	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Documents	Service book (Wartungsnachweise fehlen) - No deduction
2	Door - rear right side	Door - Abrasion - Cover / polish
3	Equipment	Tirefit filler - Expired - Replace
4	Seat - front	Backrest cover - left side - Abrasion - Loss in value
5	Seat - front	Seat cover - left side - Abrasion - Loss in value
6	Sill - left side	Trim - Scratched - Smart repair
7	Vehicle glazing	Windscreen - Stone chips - Replace
8	Bonnet	Bonnet - Scratch(es) - Repair and paint

Wear and tear

No.	Component group	Description
1	Interior	Interior - Abrasion - No deduction
2	Body	Body (Steinschläge) - Scratch(es) - No deduction
3	Rear bumper	Rear bumper - Scratched - No deduction

Missing parts

Missing part

Previous damages

No.	Previous damage
1	Front, Rear, Provided by user / customer

Detected repainting

No.	Location
1	Door - rear right side

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 25 Apr 2025

Protocol number: 39479475

Delivery date: 25 Apr 2025



Auto Plus

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98H	Pirelli	Winter tyres	4mm - 4mm	o.k.	
2	225/50 R17 98H	Dunlop	Winter tyres	5mm - 5mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	245/40 R18 93Y	Pirelli	Summer tyres	3mm - 3mm	o.k.	
2	245/40 R18 93Y	Pirelli	Summer tyres	6mm - 6mm	o.k.	

Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					06/2024

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, n. i. O.

Fahrzeug war zum Zeitpunkt der Besichtigung regennass, weitere Beschädigungen können nicht ausgeschlossen werden

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 25 Apr 2025

Protocol number: 39479475

Delivery date: 25 Apr 2025



Auto Plus

Vehicle details

Manufacturer	Audi	Inspection condition	conditional: light/moisture/dirt
Type / Model	A4 Avant	Mileage (Read)	54,233 km
Vehicle Identification number	WAUZZZF47MA003146	First registration	21 Aug 2020

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior




Figure 10: Misc.




Figure 11: Misc.



Figure 12: Misc.




Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 25 Apr 2025
Protocol number: 39479475
Delivery date: 25 Apr 2025



Auto Plus



Figure 19: Misc.



Figure 20: Misc.

Pictures of damage



Damage #2: Door - rear right side: Door - Abrasion - Cover / polish




Damage #2: Door - rear right side: Door - Abrasion - Cover / polish




Damage #2: Door - rear right side: Door - Abrasion - Cover / polish



Damage #4: Seat - front: Backrest cover - left side - Abrasion - Loss in value



Damage #4: Seat - front: Backrest cover - left side - Abrasion - Loss in value



Damage #5: Seat - front: Seat cover - left side - Abrasion - Loss in value



Damage #5: Seat - front: Seat cover - left side - Abrasion - Loss in value



Damage #6: Sill - left side: Trim - Scratched - Smart repair



Damage #6: Sill - left side: Trim - Scratched - Smart repair



Damage #7: Vehicle glazing: Windscreen - Stone chips - Replace



Damage #8: Bonnet: Bonnet - Scratch(es) - Repair and paint



Damage #8: Bonnet: Bonnet - Scratch(es) - Repair and paint

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 25 Apr 2025
Protocol number: 39479475
Delivery date: 25 Apr 2025



Auto Plus



Damage #8: Bonnet: Bonnet - Scratch(es) - Repair and paint