



WBA11FY020FP43603

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	52,887 km
Manufacturer	BMW	Next maintenance in	15,000 km
Type / Model	318i	Main inspection (Read from ZBI)	02/2026
Vehicle Identification number	WBA11FY020FP43603	Power / Engine displacement	115 kW / 1,998 ccm
First registration	16 Feb 2023	Upholstery/Colour	/
Last maintenance	10/2024, 34,191 km	Paintwork	
Fuel type	Petrol	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Sill - left side	Sill - dent(s) - Smooth repair work
2	Rear bumper	Rear bumper - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Body	Body (Steinschläge) - Scratch(es) - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction
3	Interior	Interior (Steinschläge) - Scratch(es) - No deduction
4	Interior	Interior - Abrasion - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98H	Pirelli	Winter tyres	6mm - 6mm	o.k.	
2	225/50 R17 98H	Pirelli	Winter tyres	5mm - 5mm	o.k.	

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 29 Apr 2025
Protocol number: 39505755
Delivery date: 29 Apr 2025



Auto Plus

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98Y	Bridgestone	Summer tyres	6mm - 6mm	o.k.	
2	225/50 R17 98Y	Bridgestone	Summer tyres	5mm - 5mm	o.k.	

Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					01/2028

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 29 Apr 2025
Protocol number: 39505755
Delivery date: 29 Apr 2025



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	318i	Mileage (Read)	52,887 km
Vehicle Identification number	WBA11FY020FP43603	First registration	16 Feb 2023

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear




Figure 5: Interior




Figure 6: Interior

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 29 Apr 2025
Protocol number: 39505755
Delivery date: 29 Apr 2025



Figure 7: Interior



Figure 8: Interior




Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.



Figure 12: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 29 Apr 2025
Protocol number: 39505755
Delivery date: 29 Apr 2025



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 29 Apr 2025
Protocol number: 39505755
Delivery date: 29 Apr 2025



Figure 19: Misc.




Figure 20: Misc.


Pictures of damage



Damage #1: Sill - left side: Sill - dent(s) - Smooth repair work



Damage #1: Sill - left side: Sill - dent(s) - Smooth repair work



Damage #2: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #2: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #2: Rear bumper: Rear bumper - Scratched - Repair and paint