

Vehicle details

VIN	ZFA263000 06K40306	Brand	FIAT	Maintenance date	-
Licence Plate	V2-70-LF	Model	Doblò 1/2 Cargo SX 1.3 MJ L1H1 4d	Maintenance mileage	-
Registration date	18/01/2018	Year	2018	Exterior Color	White Solid
Odometer	72 456 km	Engine size	1248	interior Color	Grey
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	4	Gears	5		

Inspection Details

Inspection date	07/04/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element


Spare wheel (wheel & tyre)	✓
----------------------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Viking 185/65/15 Summer 3.0 mm



Viking 185/65/15 Summer 3.0 mm



Pirelli 185/65/15 Summer 5.0 mm



Pirelli 185/65/15 Summer 5.0 mm

Exterior

1



Part	Door
Position	Back left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

2



Part	Wing
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

3



Part	Door
Position	Side right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

4



Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

5



Part	Wing
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

6



Part	Bonnet
Position	-
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair