



WBA51BN070CH09630

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	120,273 km
Manufacturer	BMW	Next maintenance in	15,000 km
Type / Model	520d xDrive	Main inspection (Report on hand)	03/2026
Vehicle Identification number	WBA51BN070CH09630	Power / Engine displacement	140 kW / 1,995 ccm
First registration	21 Apr 2021	Upholstery/Colour	/
Last maintenance	01/2025, 113,816 km	Paintwork	
Fuel type	Hybrid Diesel / E	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Interior	Boot cover / roller cover (Fehlt) - No deduction
2	2nd wheel set	2 alloy rims - Scratched - Loss in value

Wear and tear

No.	Component group	Description
1	Door - front left side	Door edge - Scratched - No deduction
2	Door - front right side	Door edge - Scratch(es) - No deduction
3	Body	Body (Steinschläge) - Scratch(es) - No deduction
4	Vehicle glazing	Windscreen (Steinschläge) - No deduction

Missing parts

Missing part

Previous damages

No.	Previous damage
1	Front, Rear, Provided by user / customer

Detected repainting

No.	Location
1	Door - rear right side, Professionally carried out

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/55 R17 101V	Goodyear	Winter tyres	8mm - 8mm	o.k.	
2	225/55 R17 101V	Goodyear	Winter tyres	8mm - 8mm	o.k.	

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 15 Apr 2025

Protocol number: 39360055

Delivery date: 15 Apr 2025



Auto Plus

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/55 R17 101Y	Goodyear	Summer tyres	4mm - 4mm	o.k.	
2	225/55 R17 101Y	Goodyear	Summer tyres	3mm - 3mm	o.k.	

Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					02/2027

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und

Richtigkeit der angezeigten Ausstattung.

Techn. Änderungen vorbehalten

Das Fahrzeug weist dem Alter, der Laufleistung und dem

Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, N.i.O

Fahrzeug war zum Zeitpunkt der Besichtigung regennass, weitere Beschädigungen können nicht ausgeschlossen werden.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 15 Apr 2025

Protocol number: 39360055

Delivery date: 15 Apr 2025



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	conditional: light/moisture/dirt
Type / Model	520d xDrive	Mileage (Read)	120,273 km
Vehicle Identification number	WBA51BN070CH09630	First registration	21 Apr 2021

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 15 Apr 2025
Protocol number: 39360055
Delivery date: 15 Apr 2025



Figure 7: Interior



Figure 8: Interior




Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.



Figure 12: Misc.




Figure 13: Misc.



Figure 14: Misc.




Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 15 Apr 2025
Protocol number: 39360055
Delivery date: 15 Apr 2025



Figure 25: Misc.

Pictures of damage



Damage #1: Interior: Boot cover / roller cover (Fehlt) - No deduction



Damage #2: 2nd wheel set: 2 alloy rims - Scratched - Loss in value



Damage #2: 2nd wheel set: 2 alloy rims - Scratched - Loss in value



Damage #2: 2nd wheel set: 2 alloy rims - Scratched - Loss in value