



Brand:	Dacia	Mileage(km):	163270
Model:	Logan mcv	Number of doors:	5
Model type:	0.9 TCe Laureate Org.NL	Vehicle length (cm):	
License plate:	NG217V	Vehicle width (cm):	
Report code:	6255	Vehicle height (cm):	
Chassis number:	UU17SDL1556066255	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	25/01/2017	Power(kw):	66
First NL req.:	25/01/2017	Transmission	Manual
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears	5
Weight (kg)(kg):	1146	Displacement(cc):	898
Empty weight(kg):	1046	Number of cylinders:	3
Wheelbase (cm)(cm):	263	Fuel type:	Petrol
Top speed (km/h):	175	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.8	EU category:	Euro 6
Cons. outside the city (l/100 km):	4.3	Energy label:	B
Average consumption (l/100 km):	4.9	NL Tax Rate %:	
Acceleration (s):	11.1	CO2 (g/km):	109
Cargo space (l):	1146	Nb. of Axles:	2
Perm. max weight (kg):	1620	APK date:	25/01/2026

opties

- | | | |
|--------------------------------------------------------------------|------------------------------------------------------------------------|-------------------------------------------------------------------------|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Radio/CD player |
| <input checked="" type="checkbox"/> Towing hook | <input checked="" type="checkbox"/> Halogen headlights | <input checked="" type="checkbox"/> Radio/CD/MP3 player |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Bluetooth car kit |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Cruise control |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Aux connection | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Bluetooth streaming | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Roof rail (black) | <input checked="" type="checkbox"/> DAB+ | <input checked="" type="checkbox"/> Leather steering wheel |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer		185/65 R15	tyfoon	5
Tire left rear	Summer		185/65 R15	tyfoon	5
Tire right front	Summer		185/65 R15	tyfoon	5
Tire right rear	Summer		185/65 R15	tyfoon	5

Additional information

- | | | | | |
|-------------------|---|-------------------------------------|----------------------------------------------|----------------------------------------------------------------------|
| No. of keys: | 2 | <input type="checkbox"/> Luxury key | <input type="checkbox"/> Instruction booklet | <input checked="" type="checkbox"/> Airco works |
| Interior color: | | | Maintenance booklet: | <input checked="" type="checkbox"/> Odorless |
| Upholstery: | | | | <input checked="" type="checkbox"/> Clean inside (Interior is clean) |
| No. of seats: | 5 | | Stamp date: | <input checked="" type="checkbox"/> Display ok |
| No. of headrests: | 5 | | Last turn mileage(km): | <input checked="" type="checkbox"/> Vehicle special usage (None) |

Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Polishing)

🔧 Damages

⊕ Not acceptable



Front bumper - Scratch



Rear bumper - Scratch



Rear right screen - Dent



Front bumper - Ontzet




Ketting Geeft Bijgeluid

🔧 Damages

⊕ Acceptable

⚙ Extra options







AUTOF[▲]CTOR
SOFTWARE FOR AUTOMOTIVE