



Brand:	Citroen	Mileage(km):	85940
Model:	C5 Aircross	Number of doors:	5
Model type:	1.2 PureTech Feel	Vehicle length (cm):	
License plate:	H995DG	Vehicle width (cm):	
Report code:	4704	Vehicle height (cm):	
Chassis number:	VR7ARHNSJKL104704	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	06/01/2020	Power(kw):	96
First NL reg.:	06/01/2020	Transmission	Manual
Color:	White <input type="checkbox"/> Metallic	Number of gears	6
Weight (kg)(ka):	1479	Displacement(cc):	1199
Empty weight(kg):	1379	Number of cylinders:	3
Wheelbase (cm)(cm):	273	Fuel type:	Petrol
Top speed (km/h):	195	Fuel tank capacity:	
Cons. in the city (l/100 km):	6.1	EU category:	Euro 6
Cons. outside the city (l/100 km):	4.8	Energy label:	C
Average consumption (l/100 km):	5.3	NL Tax Rate %:	
Acceleration (s):	11.6	CO2 (g/km):	121
Cargo space (l):	1479	Nb. of Axles:	2
Perm. max weight (kg):	1940	APK date:	06/01/2026

opties

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Airconditioning in the back |
| <input checked="" type="checkbox"/> Digital dashboard | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Climate control |
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> Exterior mirrors with step light | <input checked="" type="checkbox"/> Climate control (digital) |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Privacy glass | <input checked="" type="checkbox"/> Climate control (L/R separated) |
| <input checked="" type="checkbox"/> bots waarschuwing systeem | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Rear view camera | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Electrically folding mirrors |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Front parking sensors | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Adjustable lumbar support driver's seat |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> DAB+ | <input checked="" type="checkbox"/> Adjustable lumbar support passenger seat |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> Radio | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> WiFi | <input checked="" type="checkbox"/> Lane assistance |
| <input checked="" type="checkbox"/> Roof rail (silver) | <input checked="" type="checkbox"/> Cruise control | <input checked="" type="checkbox"/> Pedestrian safety system |
| <input checked="" type="checkbox"/> Halogen headlights | <input checked="" type="checkbox"/> Airconditioning | <input checked="" type="checkbox"/> Dead angle assistance |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	235/55 R18	Vredestein	3
Tire left rear	Winter	Alloy	235/55 R18	Vredestein	6
Tire right front	Winter	Alloy	235/55 R18	Vredestein	3
Tire right rear	Winter	Alloy	235/55 R18	Vredestein	6

Additional information

No. of keys:	2 <input type="checkbox"/> Luxury key <input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black Maintenance booklet:	<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder	<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5 Stamp date:	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5 Last turn mileage(km):	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)

☐ Clean outside

 Damages

 Not acceptable



Front bumper - Scratch



Front left door - Restyle dent



Left C- column - Restyle dent



Right C- column - Paint repair



Front left door - Dent



Rear right door - Scratch



Front left door - Scratch

 Damages

 Acceptable

 Extra options





