



Brand:	Citroen	Mileage(km):	64606
Model:	C3	Number of doors:	5
Model type:	1.2 PureTech Feel	Vehicle length (cm):	
License plate:	L943ZR	Vehicle width (cm):	
Report code:	5544	Vehicle height (cm):	
Chassis number:	VF7SXHMRVMT605544	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	20/09/2021	Power(kw):	61
First NL reg.:	20/09/2021	Transmission	Manual
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears	5
Weight (kg)(kq):	1055	Displacement(cc):	1199
Empty weight(kq):	955	Number of cylinders:	3
Wheelbase (cm)(cm):	254	Fuel type:	Petrol
Top speed (km/h):	166	Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	
Cons. outside the city (l/100 km):		Energy label:	B
Avarage consumption (l/100 km):		NL Tax rate %:	
Acceleration (s):	13.3	CO2 (g/km):	1
Cargo space (l):	1055	Nb. of Axles:	2
Perm. max weight (kg):	1540	APK date:	20/09/2025

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Cruise control |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> LED headlights | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> bots waarschuwing systeem | <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Climate control |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Climate control (digital) |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Electrically folding mirrors |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> DAB+ | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Lane assistance |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> Radio | <input checked="" type="checkbox"/> Pedestrian safety system |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> WiFi | |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Steel	205/55 R16	Dunlop	3
Tire left rear	Summer	Steel	205/55 R16	Dunlop	5
Tire right front	Summer	Steel	205/55 R16	Dunlop	3
Tire right rear	Summer	Steel	205/55 R16	Dunlop	5

Additional information


No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	11/06/2024	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	50174	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

🔧 Damages

⊗ Not acceptable



Front left screen - Paint repair




Front bumper - Scratch



Tailgate/ lid - Dent



Rear right screen - Paint repair



Front left door - Restyle dent



Rear right door - Paint repair



Front left door - Paint repair

🔧 Damages

⊗ Acceptable

⚙️ Extra options



