



Brand:	BMW	Mileage(km):	116800
Model:	X5	Number of doors:	5
Model type:	M Competition BMW Individual Ametrin Metallic Softclose HUD Stoelverwarming + ventilatie Surround view Harman/Kardon	Vehicle length (cm):	
		Vehicle width (cm):	
		Vehicle height (cm):	
License plate:	P786GT	Vehicle body type:	
Report code:	4945	Traction:	Front+Rear
Chassis number:	WBSJU010609H04945	Power(kw):	460
Type of vehicle:	Luxury	Transmission	Automatic
First int. reg.:	25/06/2021	Number of gears	
First NL reg.:	14/04/2022	Displacement(cc):	4395
Color:	Red <input checked="" type="checkbox"/> Metallic	Number of cylinders:	8
Weight (kg)(kg):	2410	Fuel type:	Petrol
Empty weight(kg):	2310	Fuel tank capacity:	
Wheelbase (cm)(cm):	297	EU category:	Euro 6
Top speed (km/h):	290	Energy label:	G
Cons. in the city (l/100 km):		NL Tax Rate %:	
Cons. outside the city (l/100 km):		CO2 (g/km):	303
Average consumption (l/100 km):		Nb. of Axles:	2
Acceleration (s):	3.8	APK date:	25/06/2025
Cargo space (l):	2410		
Perm. max weight (kg):	3000		

opties

<input checked="" type="checkbox"/> Alloy wheels	<input checked="" type="checkbox"/> Rear view camera	<input checked="" type="checkbox"/> Electrically adjustable mirrors
<input checked="" type="checkbox"/> Leather upholstery	<input checked="" type="checkbox"/> Rear parking sensors	<input checked="" type="checkbox"/> Electrically adjustable driver's seat (including memory)
<input checked="" type="checkbox"/> Air suspension	<input checked="" type="checkbox"/> Front parking sensors	<input checked="" type="checkbox"/> Electrically adjustable passenger seat (including memory)
<input checked="" type="checkbox"/> Digital dashboard	<input checked="" type="checkbox"/> Rear-seat folding (unequal parts)	<input checked="" type="checkbox"/> Electrically heated driver's seat
<input checked="" type="checkbox"/> Licht Sensor	<input checked="" type="checkbox"/> Luggage cover	<input checked="" type="checkbox"/> Electrically heated passenger seat
<input checked="" type="checkbox"/> bots waarschuwing systeem	<input checked="" type="checkbox"/> Trunk opens electrically	<input checked="" type="checkbox"/> Central armrest front
<input checked="" type="checkbox"/> ABS	<input checked="" type="checkbox"/> Aux connection	<input checked="" type="checkbox"/> Sport seats
<input checked="" type="checkbox"/> Airbag(s)	<input checked="" type="checkbox"/> USB connection	<input checked="" type="checkbox"/> Ventilation driver's seat
<input checked="" type="checkbox"/> Audio	<input checked="" type="checkbox"/> Bluetooth streaming	<input checked="" type="checkbox"/> Ventilation passenger seat
<input checked="" type="checkbox"/> Central locking system	<input checked="" type="checkbox"/> DAB+	<input checked="" type="checkbox"/> Extendable passenger seat
<input checked="" type="checkbox"/> Harman Kardon	<input checked="" type="checkbox"/> Bluetooth car kit	<input checked="" type="checkbox"/> Extendable driver's seat
<input checked="" type="checkbox"/> Fog lamps	<input checked="" type="checkbox"/> WiFi	<input checked="" type="checkbox"/> Adjustable lumbar support driver's seat
<input checked="" type="checkbox"/> Power steering	<input checked="" type="checkbox"/> Cruise control	<input checked="" type="checkbox"/> Adjustable lumbar support passenger seat
<input checked="" type="checkbox"/> Front seats adjustable in height	<input checked="" type="checkbox"/> Head-up Display	<input checked="" type="checkbox"/> Audio control on the steering wheel
<input checked="" type="checkbox"/> Multifunctional steering wheel	<input checked="" type="checkbox"/> Sports package (interior)	<input checked="" type="checkbox"/> Electrically adjustable steering wheel
<input checked="" type="checkbox"/> Remote central locking	<input checked="" type="checkbox"/> Airconditioning in the back	<input checked="" type="checkbox"/> Leather sports steering wheel
<input checked="" type="checkbox"/> Sports package (exterior)	<input checked="" type="checkbox"/> Climate control (L/R separated)	<input checked="" type="checkbox"/> Switch flippers
<input checked="" type="checkbox"/> Metallic finish	<input checked="" type="checkbox"/> Large screen navigation	<input checked="" type="checkbox"/> Heated steering wheel
<input checked="" type="checkbox"/> LED headlights	<input checked="" type="checkbox"/> Keyless entry	<input checked="" type="checkbox"/> Lane assistance
<input checked="" type="checkbox"/> LED rear lights	<input checked="" type="checkbox"/> Keyless entry/start/stop	<input checked="" type="checkbox"/> Pedestrian safety system
<input checked="" type="checkbox"/> Privacy glass	<input checked="" type="checkbox"/> Electrically operated rear windows	<input checked="" type="checkbox"/> Dead angle assistance
<input checked="" type="checkbox"/> Rain sensor	<input checked="" type="checkbox"/> Electrically operated front windows	
<input checked="" type="checkbox"/> Rear wiper	<input checked="" type="checkbox"/> Electrically folding mirrors	

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	295/35 R21	Michelin	3
Tire left rear	Summer	Alloy	315/30 R22	Michelin	3
Tire right front	Summer	Alloy	295/35 R21	Michelin	3
Tire right rear	Summer	Alloy	315/30 R22	Michelin	3

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	White	Maintenance booklet:	(serviceboekje (digitaal))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)

No. of seats:	5	Stamp date:	26/03/2024	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	81973	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Polishing)

Damages

 Not acceptable



Front bumper - Scratch



Front left rim - Scratch



Rear left door - Restyle dent



Rear left rim - Scratch



Rear bumper - Break



Tailgate/ lid - Dent



Tailgate/ lid - Scratch



Rear right rim - Scratch



Front right rim - Scratch



Right sill - Scratch

Damages

 Acceptable

Extra options





