



Brand:	Audi	Mileage(km):	190157
Model:	A3 Limousine	Number of doors:	4
Model type:	1.0 TFSI Pro Line Org.NL	Vehicle length (cm):	
License plate:	KG661D	Vehicle width (cm):	
Report code:	2122	Vehicle height (cm):	
Chassis number:	WAUZZZ8V0H1012122	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	30/08/2016	Power(kw):	85
First NL req.:	30/08/2016	Transmission	Manual
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears	6
Weight (kg)(kg):	1260	Displacement(cc):	999
Empty weight(kg):	1160	Number of cylinders:	3
Wheelbase (cm)(cm):	264	Fuel type:	Petrol
Top speed (km/h):	211	Fuel tank capacity:	
Cons. in the city (l/100 km):	5.5	EU category:	Euro 6
Cons. outside the city (l/100 km):	3.8	Energy label:	A
Average consumption (l/100 km):	4.4	NL Tax Rate %:	25
Acceleration (s):	9.9	CO2 (g/km):	103
Cargo space (l):	1260	Nb. of Axles:	2
Perm. max weight (kg):	1735	APK date:	30/08/2025

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Bluetooth car kit |
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> Xenon headlights | <input checked="" type="checkbox"/> Cruise control |
| <input checked="" type="checkbox"/> Towing hook | <input checked="" type="checkbox"/> Xenon headlights (adaptive) | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Headlight washers | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Removable rear windows | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Aux connection | <input checked="" type="checkbox"/> Leather sports steering wheel |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> USB connection | |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Radio/CD player | |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	205/55 R16		6
Tire left rear	Summer	Alloy	205/55 R16		6
Tire right front	Summer	Alloy	205/55 R16		6
Tire right rear	Summer	Alloy	205/55 R16		6

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	10/01/2025	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	186615	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☐ Clean outside



Front left rim - Scratch



Front bumper - Scratch



Front bumper - Scratch



Left tailgate - Vocht



Rear bumper - Scratch









Rear right door - Scratch

🔧 Damages

⊕ Acceptable

⚙️ Extra options







AUTOF[▲]CTOR
SOFTWARE FOR AUTOMOTIVE