



WAUZZZF7L2126991

Vehicle details

Operator		Inspection condition	conditional: light/ moisture/dirt
License number		Mileage (Read)	112,832 km
Manufacturer	Audi	Next maintenance in	6,900 km
Type / Model	Q5 50 TFSI e S tronic quattro Sports Utility Vehicle5-türig 1984 ccm 299 PS / 220 KW Elektrisch 7-Gang Automatik	Main inspection	
Vehicle Identification number	WAUZZZF7L2126991	Power / Engine displacement	/ 1,984 ccm
First registration	9 Dec 2020	Upholstery/Colour	Leather / Black
Last maintenance		Paintwork	White
Fuel type	Hybrid Petrol / E	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Door - rear right side	Door handle - outside - Scratched - Smart repair
2	Door - rear left side	Door edge - Scratched - Smart repair
3	Misc.	Main inspection (Bescheinigung fehlt) - No evidence - Perform
4	Side panel - rear left side	Wheel well extension - Scratched - Replace
5	Rear bumper	Rear bumper - Scratched - Repair and paint
6	Door - rear right side	Door - Scratched - Repair and paint
7	Bonnet	Bonnet - Scratched - Repair and paint
8	Vehicle glazing	Windscreen with rain sensor - Broken / torn - Replace

Wear and tear

No.	Component group	Description
The vehicle shows traces of wear and tear corresponding to its age and purpose		

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	



Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	235/60 R18 107H	Goodyear	Winter tyres	6mm - 6mm	o.k.	o.k.
2	235/60 R18 107H	Goodyear	Winter tyres	7mm - 7mm	o.k.	o.k.

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	235/60 R18 103V	Michelin	Summer tyres	5mm - 5mm	o.k.	o.k.
2	235/60 R18 103V	Michelin	Summer tyres	5mm - 5mm	o.k.	o.k.

The wear and tear condition and possible damages to the tyres are considered in the value.

Equipment

Equipment

Description
Automatic air conditioning
Navigation unit with map view
Radio DAB

Comments

Für die Richtig- und Vollständigkeit der Basisdaten - wird keine Gewähr übernommen!

Ausstattungsliste nicht verfügbar.

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten.
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.



Vehicle details

Manufacturer	Audi	Inspection condition	conditional: light/ moisture/dirt
Type / Model	Q5 50 TFSI e S tronic quattro Sports Utility Vehicle5-türig 1984 ccm 299 PS / 220 KW Elektrisch 7-Gang Automatik	Mileage (Read)	112,832 km
Vehicle Identification number	WAUZZZFY7L2126991	First registration	9 Dec 2020

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior




Figure 6: Interior




Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Interior



Figure 11: Interior




Figure 12: Interior



Figure 13: Interior




Figure 14: VIN



Figure 15: Accessories



Figure 16: Accessories




Figure 17: Accessories




Figure 18: Documents



Figure 19: Mounted tyres



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.

Pictures of damage



Damage #2: Door - rear left side: Door edge - Scratched - Smart repair



Damage #4: Side panel - rear left side: Wheel well extension - Scratched - Replace



Damage #4: Side panel - rear left side: Wheel well extension - Scratched - Replace



Damage #5: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage #5: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage #5: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #6: Door - rear right side: Door - Scratched - Repair and paint



Damage #6: Door - rear right side: Door - Scratched - Repair and paint



Damage #7: Bonnet: Bonnet - Scratched - Repair and paint



Damage #6: Door - rear right side: Door - Scratched - Repair and paint



Damage #7: Bonnet: Bonnet - Scratched - Repair and paint



Damage #7: Bonnet: Bonnet - Scratched - Repair and paint

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 29 Apr 2025
Protocol number: 39653101



Damage #8: Vehicle glazing: Windscreen with rain sensor - Broken / torn - Replace