



WBA68FF0808E62837

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	11,417 km
Manufacturer	BMW	Next maintenance in	20,000 km
Type / Model	3er-Reihe 330i Automatic Limousine4-türig	Main inspection	
Vehicle Identification number	WBA68FF0808E62837	Power / Engine displacement	/ 1,998 ccm
First registration	19 Jul 2024	Upholstery/Colour	Leather / Red
Last maintenance		Paintwork	Grey
Fuel type	Petrol	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Documents	Owner's manual (fehlt) - Replace
2	Front bumper	Front bumper - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
The vehicle shows traces of wear and tear corresponding to its age and purpose		

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98H	Goodyear	Winter tyres	7mm - 7mm	o.k.	o.k.
2	225/50 R17 98H	Goodyear	Winter tyres	7mm - 7mm	o.k.	o.k.

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/45 R18 95Y	Bridgestone	Summer tyres	5mm - 5mm	o.k.	o.k.
2	255/40 R18 99Y	Bridgestone	Summer tyres	5mm - 5mm	o.k.	o.k.

The wear and tear condition and possible damages to the tyres are considered in the value.

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 30 Apr 2025
Protocol number: 39623210



Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten.
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 30 Apr 2025
Protocol number: 39623210



Vehicle details

Manufacturer	BMW	Inspection condition	conditional: light/moisture/dirt
Type / Model	3er-Reihe 330i Automatic Limousine4-türig	Mileage (Read)	11,417 km
Vehicle Identification number	WBA68FF0808E62837	First registration	19 Jul 2024

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior




Figure 8: Interior




Figure 9: Interior



Figure 10: Interior




Figure 11: Interior



Figure 12: Interior



Figure 13: VIN




Figure 14: Documents



Figure 15: Mounted tyres




Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 30 Apr 2025
Protocol number: 39623210



Figure 19: Misc.


TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 30 Apr 2025
Protocol number: 39623210



Pictures of damage



Damage #2: Front bumper: Front bumper - Scratched - Repair and paint