



WBA31AX020FS55104

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	26,012 km
Manufacturer	BMW	Next maintenance in	-5,000 km
Type / Model	420d xDrive Gran Coupé A Schräghecklimousine5-türig	Main inspection	
Vehicle Identification number	WBA31AX020FS55104	Power / Engine displacement	/ 1,995 ccm
First registration	27 Feb 2024	Upholstery/Colour	Alcantara / Leather / Black
Last maintenance		Paintwork	Grey
Fuel type	Diesel	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - rear right side - Scratched - Loss in value
2	Wheel / tyres	Tyre - rear right side - Damaged - Replace
3	Wheel / tyres	Tyre - front right side - Damaged - Replace
4	Misc.	Inspection / maintenance - Due - Perform
5	Wheel / tyres	Alloy rim - front right side - Scratched - Replace

Wear and tear

No.	Component group	Description
The vehicle shows traces of wear and tear corresponding to its age and purpose		

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	245/35 R20 95Y	Michelin	Summer tyres	5mm - 5mm	o.k.	o.k.
2	255/35 R20 97Y	Michelin	Summer tyres	5mm - 5mm	o.k.	o.k.



Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	245/40 R19 98V	Michelin	Winter tyres	5mm - 5mm	o.k.	o.k.
2	255/40 R19 100V	Michelin	Winter tyres	6mm - 6mm	o.k.	o.k.

The wear and tear condition and possible damages to the tyres are considered in the value.

Equipment

Equipment

Description
Automatic air conditioning
Navigation unit with map view
Radio DAB

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten.
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 7 May 2025
Protocol number: 39623475



Vehicle details

Manufacturer	BMW	Inspection condition	conditional: light/moisture/dirt
Type / Model	420d xDrive Gran Coupé A Schräghecklimousine5-türig	Mileage (Read)	26,012 km
Vehicle Identification number	WBA31AX020FS55104	First registration	27 Feb 2024

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Interior




Figure 11: Interior




Figure 12: Interior



Figure 13: Interior




Figure 14: VIN



Figure 15: Accessories



Figure 16: Accessories



Figure 17: Documents




Figure 18: Mounted tyres



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.


Pictures of damage




Damage #1: Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value



Damage #2: Wheel / tyres: Tyre - rear right side - Damaged - Replace



Damage #3: Wheel / tyres: Tyre - front right side - Damaged - Replace



Damage #4: Misc.: Inspection / maintenance - Due - Perform



Damage #5: Wheel / tyres: Alloy rim - front right side - Scratched - Replace