



WBA31BN000CP14723

Vehicle details

Operator		Inspection condition	conditional: light/ moisture/dirt
License number		Mileage (Read)	32,520 km
Manufacturer	BMW	Next maintenance in	13,000 km
Type / Model	5er-Reihe 520d Touring A Kombi5-türig 1995 ccm 190 PS / 140 KW Diesel 8-Gang Automatik	Main inspection	
Vehicle Identification number	WBA31BN000CP14723	Power / Engine displacement	/ 1,995 ccm
First registration	4 Aug 2023	Upholstery/Colour	Leather / Black
Last maintenance		Paintwork	White
Fuel type	Diesel	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratched - Repair and paint
2	2nd wheel set	1 alloy rim - Scratched - Replace
3	Front bumper	Front bumper - Deformed - Replace

Wear and tear

No.	Component group	Description
The vehicle shows traces of wear and tear corresponding to its age and purpose		

Missing parts

Missing part

Previous damages

No.	Previous damage
1	Side right, Provided by user / customer, from 13 Jul 2024

Detected repainting

No.	Location
1	Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent
2	Door - rear right side, Professionally carried out, Invoice of repair done Non-existent
3	Door - front right side, Professionally carried out, Invoice of repair done Non-existent



Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/55 R17 97H	Goodyear	Winter tyres	6mm - 6mm	o.k.	o.k.
2	225/55 R17 97H	Goodyear	Winter tyres	7mm - 7mm	o.k.	o.k.

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	245/45 R18 100Y	Bridgestone	Summer tyres	5mm - 5mm	o.k.	o.k.
2	245/45 R18 100Y	Bridgestone	Summer tyres	5mm - 5mm	o.k.	o.k.

The wear and tear condition and possible damages to the tyres are considered in the value.

Equipment

Equipment

Description
Automatic air conditioning
Navigation unit with map view
Radio DAB

Comments

Für die Richtig- und Vollständigkeit der Basisdaten - wird keine Gewähr übernommen!

Ausstattungsliste nicht verfügbar.

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten.
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, n. i. O.



Vehicle details

Manufacturer	BMW	Inspection condition	conditional: light/moisture/dirt
Type / Model	5er-Reihe 520d Touring A Kombi5-türig 1995 ccm 190 PS / 140 KW Diesel 8-Gang Automatik	Mileage (Read)	32,520 km
Vehicle Identification number	WBA31BN000CP14723	First registration	4 Aug 2023

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Interior



Figure 11: Interior



Figure 12: Interior



Figure 13: VIN



Figure 14: Accessories



Figure 15: Accessories




Figure 16: Documents



Figure 17: Mounted tyres



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.


Pictures of damage



Damage #1: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage #1: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage #1: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #2: 2nd wheel set: 1 alloy rim - Scratched - Replace



Damage #3: Front bumper: Front bumper - Deformed - Replace



Damage #3: Front bumper: Front bumper - Deformed - Replace

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 14 May 2025
Protocol number: 39752420



Damage #3: Front bumper: Front bumper - Deformed - Replace


Pictures of repainting



Repainting 1: Side panel - rear right side



Repainting 2: Door - rear right side



Repainting 3: Door - front right side