



WBA11AJ090CG87306

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	116,940 km
Manufacturer	BMW	Next maintenance in	25,000 km
Type / Model	530d	Main inspection (Report not on hand)	04/2026
Vehicle Identification number	WBA11AJ090CG87306	Power / Engine displacement	210 kW / 2,993 ccm
First registration	1 Apr 2021	Upholstery/Colour	/
Last maintenance	02/2025, 112,134 km	Paintwork	
Fuel type	Hybrid Diesel / E	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Tyre - right - Worn - No deduction
2	Wheel / tyres	Alloy rim - rear left side - Scratched - No deduction
3	Documents	Main inspection certificate (Fehlt) - Replace
4	Sill - left side	Sill - dent(s) - Smooth repair work
5	Door - rear right side	Door - Scratch(es) - Paint
6	Front bumper	Front bumper - Scratched - Repair and paint
7	Door - front left side	Door - Scratch(es) - Paint
8	Side panel - rear right side	Side panel - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Body	Body - Stone chips - No deduction
2	Body	Body - Scratch(es) - No deduction
3	Interior	Interior - Abrasion - No deduction
4	Vehicle glazing	Windscreen - Stone chips - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 28 Apr 2025

Protocol number: 39481154

Delivery date: 28 Apr 2025



Auto Plus

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	245/45 R18 100V	Pirelli	Winter tyres	6mm - 6mm	o.k.	
2	245/45 R18 100V	Pirelli	Winter tyres	4mm - 4mm	Not o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	245/45 R18 100Y	Pirelli	Summer tyres	5mm - 5mm	o.k.	
2	275/40 R18 103Y	Pirelli	Summer tyres	4mm - 4mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und

Richtigkeit der angezeigten Ausstattung.

Techn. Änderungen vorbehalten

Das Fahrzeug weist dem Alter, der Laufleistung und dem

Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 28 Apr 2025
Protocol number: 39481154
Delivery date: 28 Apr 2025



Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	530d	Mileage (Read)	116,940 km
Vehicle Identification number	WBA11AJ090CG87306	First registration	1 Apr 2021

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear




Figure 5: Interior



Figure 6: Interior



Figure 7: Interior




Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.





Figure 22: Misc.


Pictures of damage



Damage #1: Wheel / tyres: Tyre - right - Worn - No deduction



Damage #1: Wheel / tyres: Tyre - right - Worn - No deduction



Damage #2: Wheel / tyres: Alloy rim - rear left side - Scratched - ... deduction



Damage #2: Wheel / tyres: Alloy rim - rear left side - Scratched - No deduction



Damage #2: Wheel / tyres: Alloy rim - rear left side - Scratched - ... deduction



Damage #4: Sill - left side: Sill - dent(s) - Smooth repair work



Damage #4: Sill - left side: Sill - dent(s) - Smooth repair work



Damage #4: Sill - left side: Sill - dent(s) - Smooth repair work




Damage #5: Door - rear right side: Door - Scratch(es) - Paint



Damage #5: Door - rear right side: Door - Scratch(es) - Paint



Damage #6: Front bumper: Front bumper - Scratched - Repair and paint



Damage #6: Front bumper: Front bumper - Scratched - Repair and paint



Damage #6: Front bumper: Front bumper - Scratched - Repair and paint



Damage #6: Front bumper: Front bumper - Scratched - Repair and paint




Damage #6: Front bumper: Front bumper - Scratched - Repair and paint



Damage #7: Door - front left side: Door - Scratch(es) - Paint



Damage #7: Door - front left side: Door - Scratch(es) - Paint



Damage #7: Door - front left side: Door - Scratch(es) - Paint

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 28 Apr 2025
Protocol number: 39481154
Delivery date: 28 Apr 2025




Auto Plus



Damage #8: Side panel - rear right side: Side panel - Scratched -
Repair and paint



Damage #8: Side panel - rear right side: Side panel - Scratch...
- Repair and paint



Damage #8: Side panel - rear right side: Side panel - Scratched -
Repair and paint