



status report

Customer:	Allane SE HCBE	Off. Mark :	A-OP 104E
Report number:	0000000833694-EN968		
reference number:	30923681		

Vehicle Data

Hyundai Ioniq 5 (05.2021->) Dynamiq Elektro

Vehicle identification number .:	KMHKN81EFPU126026	mileage read:	34533 km
First Registration / construction Year:	21.12.2022 / 2022	Inspection date/place:	02.04.2025 81825 München
Bodywork:	Cars	Body type:	station wagon
fuel:	Electric	Transmission type:	Automatic
GPS sat nav disk:	-	Displacement / power:	0 ccm / 168 kW (228 PS)
Drive type:	Rear-wheel drive	Paint:	Digital Teal / MIC
Type of paint:	Metallic	Doors / seats:	5 / 5
Number of keys:	2	Next HU / AU:	5-20 / 5-20
cushion type:	Substance	Service book available:	Yes
Interior Color:	Gray	Maintained service book:	-
smoking vehicle:	No	Last service km / on the:	- / -
Vehicle roadworthy:	Yes	Submitted vehicle documents:	Registration Certificate
State outside:	2 - Good	condition inside:	2 - Good

The status Report was created impartially and to the best of my knowledge. The images listed in the status Report are part of the vehicle description regarding the equipment and the vehicle condition.



Mounted tires

	Summer tires	Aluminium original
Tyre / wheel type:		
1st axis - Left / states .	Michelin	235/55/R19/105W 6 mm
1st axis - right / states .	Michelin	235/55/R19/105W 6 mm
2nd axis - Left / states .	Michelin	235/55/R19/105W 6 mm
2nd axis - right / states .	Michelin	235/55/R19/105W 6 mm
Traffic Safety:	Roadworthy	

Series

- 3rd brake light
- Storage bag on front seat backrests
- Airbag front passenger side can be switched off
- Active brake light (ESS)
- Anti-lock braking system (ABS)
- Applikationen am Fahrzeugheck (schwarz)
- Audio system: Radio RDS
- Outside mirror electr. adjustable and heated, both
- Außenspiegel Unterschale schwarz lackiert
- Flashing light integrated in the exterior mirror
- DYNAMIQ-Paket
- Automatic switch-on for driving lights / light sensor
- Electron. Stability control (ESC) with brake assistant
- Fahrassistenz-System: aktiver Totwinkel-Assistent
- Fahrassistenz-System: Ausstiegswarnung
- Driving assistance system: Autonomous emergency braking function including turning function (FCA-JT)
- Driving assistance system: Autonomous emergency braking function including pedestrian detection (FCA-Ped.)
- Driving assistance system: parking assistance front and rear
- Driver assistance system: high beam assistant
- Driving Assistance System: Multi Collision Brake
- 6 Lautsprecher
- Airbag passenger side
- Airbag driver side
- Alarm system
- Drive type: rear-wheel drive
- Audio-Navigationssystem
- Outside mirror electr. anklappbar
- Exterior mirror painted
- Battery heating system
- Roof spoiler
- Rear Parking Sensors
- Electr. Brake force distribution
- Fahrassistenz-System: aktiver Spurhalteassistent (LKAS, Lane Keep Assist System)
- Fahrassistenz-System: Aufmerksamkeits-Assistent
- Fahrassistenz-System: Autobahnassistent (Highway Driving Assist, HDA)
- Driving assistance system: Autonomous emergency braking function including cyclist detection (FCA-Cyc.)
- Driver assistance system: hill start assist
- Driver assistance system: Driving profile selection (Drive Mode)
- Fahrassistenz-System: Insassenalarm (RSA)
- Driving assistance system: rear cross traffic assistant (Cross Traffic)

- Driving assistance system: Front cross traffic assistant (intersection assistant)
- Fahrassistenz-System: Spurfolgeassistent (Lane Following Assist, LFA)
- Window regulator electr. with anti-trap protection
- Fensterrahmen Zierleisten schwarz glänzend
- Luggage net in the luggage / loading space
- Getriebe für Elektrofahrzeug
- Cup holder in front
- Handschuhfach Schublade
- Rear window heatable
- HV-Batterie 77,4 kWh (Lithium-Ionen)
- Interior mirror with automatic dimming
- Isofix seats for child seat
- Automatic climate control 2 zones
- Headrests adjustable at the back
- Charging cable with Type 2 plug
- Lumbar support seat front left, electr. adjustable
- Steering wheel (leather) with multifunction
- Steering wheel with paddle shifters
- Steering column (steering wheel) longitudinally adjustable
- Headlamp leveling
- Rear air vents
- Rear center armrest
- Navigation-Based Adaptive Cruise Control (Cruise Control) with Adaptive Cruise Control (NSCC)
- Parking brake electric (EPB)
- Tires 235/55 R19 ... V
- Tire pressure monitoring system
- Rücksitzbank verschiebbar
- Schalt-/Wählhebel (Shift by Wire)
- Rain-sensing wipers
- Side airbag in front
- Seitenschutzleisten schwarz
- Power steering
- Seat front left electr. adjustable
- Seat front right height adjustable
- Fahrassistenz-System: Sicherheitssystem mit automatischem Notruf (ERA GLONASS / eCall)
- Fahrassistenz-System: Verkehrszeichenerkennung, erweitert (Geschwindigkeits-Regel-/Begrenzeranlage)
- Fensterheber elektrisch vorn und hinten, mit Auf-/Ab-Automatik
- Handsfree Bluetooth
- Luggage compartment cover / roller blind
- Getränkehalter hinten
- Pretensioners
- Rear lights LED (pixel design)
- Rear window wiper
- Induction charger for smartphone
- Instrumentenanzeige Farbdisplay 12,25 Zoll
- Body: 5-door
- Head airbag system
- Kühlergrill, Aktive Luftklappen, regelbar
- Ladevorrichtung On-Board-Lader (3-Phasen)
- Lendenwirbelstütze Sitz vorn rechts, elektr. verstellbar
- Lenkrad heizbar
- Steering column (steering wheel) height adjustable
- LED reading lights front and rear
- LM rims 7.5x19
- Mineraleffekt-Lackierung Lucid-Blue
- Center armrest front
- Notladekabel (ICCB)
- Radio reception digital (DAB +)
- Tire repair kit
- Backup camera
- Rear seat back divided / foldable
- Window fogging detection / control
- Scheinwerfer Voll-LED
- Seitenairbag vorn mitte (Central Airbag)
- Service system: Remote Services (Blue Link)
- Seatbelts height adjustable
- Seat front left height adjustable
- Seat cover / upholstery: fabric

- | | |
|--|--|
| <ul style="list-style-type: none"> • Heated seats in the front • Smartphone Schnittstelle (Apple CarPlay & Android Auto) • Start-stop button • Steckdose (12V-Anschluß) vorn • Daytime running light LED • Türgriffe außen ausfahrbar / versenkbar • USB-Anschluss hinten • Glazed tinted • Seat belt warning system, driver / passenger side • Heat pump for heating/air conditioning | <ul style="list-style-type: none"> • Smart key • Sonnenblenden mit Spiegel • Socket (12V connection) in the luggage compartment • Stoßfänger vorn mit Applikationen (schwarz) • Touchscreen color display (12.25 inches) • Door handles outside body color • USB-Anschluss Mittelkonsole • Vorheizsystem für Batterie • Immobilizer (electronic) • Central locking with remote control |
|--|--|

Special Features

- | | |
|--|---|
| <ul style="list-style-type: none"> • Assistance Package Tour
Driving assistance system: Front cross traffic assistant (intersection assistant), Fahrassistenz-System: Autobahnassistent 2.0 (Highway Driving Assist, HDA 2.0) • LED package
Pixel-LED-Scheinwerfer, LED light strip at the front, Rear lights LED (pixel design) | <ul style="list-style-type: none"> • Trunk lid/tailgate electric. operated (opening, sensor-controlled) • Mica finish / mineral effect finish |
|--|---|

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General exam



test drive:	Conducted limited Because of the conditions a short test drive could be performed only at a moderate speed . As part of the test drive further tests were carried out. The results are documented later in the report .
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed.
Mileage plausible:	Not testable Not testable
reference:	
Note Road Safe:	

Accident claims investigation

Rep. Predamages / -height gross:	No detectable A visual inspection of the outer body skin did not reveal any previous damage.
Layers of paint thickness measurement:	- -

Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview of technical examination					
Air conditioning:	Examined limited	✗	Lighting system:	examined limited	✗
Sunroof / convertible:	unavailable	✗	Seat heating:	Examined limited	✗

Damage			
	Exterior and Styling		
	Component	Damage	Rep kind
1.	Front door - left	Deep scratch	Smart repair
2.	Sidewall - Rear - Left	Dented	Refurbish and paint
3.	Rim rear - left	Deep scratch	Smart repair
4.	Rear door - left	chipped paint	Smart repair
	Others		
	Component	Damage	Rep kind
5.	Mittelkonsole Innenraum vorne mitte	Wear and tear	Without repair
6.	safety vest	Missing	Replace
7.	first aid kit	Missing	Replace
8.	warning triangle	Missing	Replace
9.	Tire-fit filler	Defective	Replace

A Pre Damage check is being made solely in the context and the possibilities of a visual inspection and measurement of paint layers without a Disassembly of components. A possible existence of pre-damages is unknown.

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage - related wear , as in normal use are inevitable (small bumps , dents , scratches) .

There shall be no liability accepted for any defect and / or remained hidden damage in terms of electronics and mechanics, as well as for fraudulent misrepresentation and concealed defects .



Hüsches Gruppe®
Die Gutachter

Photo documentation



front Left



front Right



rear Left



rear Right



trunk



Inside



instrument cluster



mileage




center console



key



key



Service book / proof



Others



Others



Others



engine compartment



rims



tires



tires



tires



tires



1. Front door - left
Deep scratch - Smart repair



2. Sidewall - Rear - Left
Dented - Refurbish and paint



3. Rim rear - left
Deep scratch - Smart repair



4. Rear door - left
chipped paint - Smart repair



5. Mittelkonsole Innenraum vorne mitte
Wear and tear - Without repair