



Brand:	Fiat	Mileage(km):	83846
Model:	500	Number of doors:	3
Model type:	1.0 Hybrid Lounge	Vehicle length (cm):	
License plate:	J267XH	Vehicle width (cm):	
Report code:	6497	Vehicle height (cm):	
Chassis number:	ZFA3120000JE06497	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	30/10/2020	Power(kw):	51
First NL reg.:	30/10/2020	Transmission	Manual
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears	6
Weight (kg)(kg):	1055	Displacement(cc):	999
Empty weight(kg):	955	Number of cylinders:	3
Wheelbase (cm)(cm):	230	Fuel type:	Petrol
Top speed (km/h):	167	Fuel tank capacity:	
Cons. in the city (l/100 km):	4.7	EU category:	Euro 6
Cons. outside the city (l/100 km):	3.4	Energy label:	B
Average consumption (l/100 km):	3.9	NL Tax Rate %:	
Acceleration (s):	13.8	CO2 (g/km):	88
Cargo space (l):	1055	Nb. of Axles:	2
Perm. max weight (kg):	1360	APK date:	12/08/2026

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> Bluetooth streaming |
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> DAB+ |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Bluetooth car kit |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Halogen headlights | <input checked="" type="checkbox"/> Radio |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Cruise control |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Climate control |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Climate control (analog) |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Rear-seat folding (equal parts) | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Start/stop system | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Leather steering wheel |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	185/55 R15	Vredestein	5
Tire left rear	Summer	Alloy	185/55 R15	Vredestein	6
Tire right front	Summer	Alloy	185/55 R15	Vredestein	5
Tire right rear	Summer	Alloy	185/55 R15	Vredestein	6

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Miscellaneous	Maintenance booklet:		<input type="checkbox"/> Odorless (Rokersgeur)
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	4	Stamp date:		<input checked="" type="checkbox"/> Display ok
No. of headrests:	4	Last turn mileage(km):		<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

Damages

⊕ Not acceptable



Grille - Break



Rear bumper - Break



Rear bumper - Break



Bestuurderstoel+Passagierstoel brandgat



Bestuurderstoel+Passagierstoel brandgat

🔧 Damages

🟢 Acceptable

⚙️ Extra options



