

Inspected by: Rob Datema



Brand:	Audi	Mileage(km):	146691
Model:	e-tron	Number of doors:	5
Mandal Arman	e-tron 55 quattro advanced 95 kWh Pano	Vehicle length (cm):	
Model type:	Trekhaak Mmeory Leder	Vehicle width (cm):	
License plate:	G056JX	Vehicle height (cm):	
Report code:	3259	Vehicle body type:	
Chassis number:	WAUZZZGE0KB003259	Traction:	Front+Rear
Type of vehicle:	Luxury	Power(kw):	265
First int. req.:	09/10/2019	Transmission	Automatic
First NL reg.:	09/10/2019	Number of gears	
Color:	Blue Metallic	Displacement(cc):	
Weight (kg)(kg):	2565	Number of cylinders:	
Empty weight(kg):	2465	Fuel type:	Electric
Wheelbase (cm)(cm):	293	Fuel tank capacity:	
Top speed (km/h):	200	EU category:	
Cons. in the city (I/100 km):		Energy label:	Α
Cons. outside the city (I/100 km):		NL Tax Rate %:	
Avarage consumption (I/100 km):		CO2 (q/km):	
Acceleration (s):	6.6	Nb. of Axles:	2
Cargo space (I):	2565	APK date:	13/07/2025
Perm. max weight (kg):	3130		

opties 🗘

>>> Alloy wheels Leather upholstery Air suspension Digital dashboard Daytime running lights Licht Sensor Towing hook bots waarschuwing systeem Anti-lock braking system ABS Airbag(s) Audio bots herkenning systeem Central locking system Start/stop system Power steering Front seats adjustable in height Multifunctional steering wheel Remote central locking Roof rail (black)

Headlight washers LED rear lights Exterior mirrors in car body color

Panoramic roof (electrical)

Exterior mirrors with step light Privacy glass

Metallic finish

LED headlights

Rear wiper ~ 360 ° camera system ${f \checkmark}$ Rear view camera ${f \sim}$ Rear parking sensors ${f \sim}$ Front parking sensors Towbar with detachable ball Rear-seat folding (equal parts) Rear-seat folding (unequal parts) Baggage separation net Luggage cover $\overline{}$ $\overline{\mathbf{v}}$ Trunk opens electrically <u>*</u> Charging cable 220V **USB** connection `**`** Bluetooth streaming DAB+ ***** Bluetooth car kit Radio ${f \sim}$ WiFi Cruise control (adaptive) $\overline{}$ Cruise control Head-up Display $\overline{\mathbf{v}}$ Black top interior Airconditioning 11111 Airconditioning in the back Climate control Climate control (analog)

Climate control (digital)

Rain sensor

Climate control (L/R separated) Large screen navigation Keyless entry Keyless entry/start/stop Keyless start/stop Electrically operated rear windows Electrically operated front windows Electrically folding mirrors Electrically adjustable mirrors Electrically adjustable driver's seat Electrically adjustable driver's seat (including memory) Electrically adjustable passenger seat Electrically heated driver's seat Electrically heated passenger seat Central armrest front Sport seats Extendable passenger seat Extendable driver's seat Adjustable lumbar support driver's seat Adjustable lumbar support passenger seat Audio control on the steering wheel Electrically adjustable steering wheel 22222 Leather steering wheel Switch flippers Heated steering wheel Lane assistance Pedestrian safety system Dead angle assistance

O lires						
Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):	
Tire left front	All weather	Alloy	265/45 R21	Vredestein	7	
Tire left rear	All weather	Alloy	265/45 R21	Vredestein	6	
Tire right front	All weather	Alloy	265/45 R21	Vredestein	7	
Tire right rear	All weather	Alloy	265/45 R21	Vredestein	6	

A Additional information	1			
No. of keys:	2	Luxury key	☐ Instruction booklet	

Interior color:	Black	Maintenance booklet:	Odorless
Upholstery:	Leder		Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	Display ok
No. of headrests:	5	Last turn mileage(km):	✓ Vehicle special usage (None)

A Cleaning

- Clean inside (Interior is clean)
- Clean outside (Cleaning)

Damages

Front bumper - Scratch

Not acceptable



Front left rim - Scratch



Front right rim - Scratch

Rear left door - Scratch



Rear left rim - Scratch



Rear left screen - Paint repair



Rear left door - Paint repair



Rear right rim - Scratch



Rear right door - Restyle dent



Windscreen - Pip




Bijgeluid Elektromotor Achterzijde

Damages


Acceptable



































































































AUTOF CTOR