



WAUZZZF54LA020770

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	102,051 km
Manufacturer	Audi	Next maintenance in	-9 Tag(e)
Type / Model	A5 Sportback	Main inspection (Read from ZBI)	08/2025
Vehicle Identification number	WAUZZZF54LA020770	Power / Engine displacement	140 kW / 1,984 ccm
First registration	13 Jul 2020	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Hybrid Petrol / E	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Door - front right side	Door - dent(s) - Smooth repair work
2	Mudguard - left side	Mudguard - left side - Scratched - Smart repair
3	Equipment	Vehicle key (1 von 2 fehlt) - Replace
4	Wing mirror - right side	Mirror housing - Damaged - Replace
5	Front bumper	Spoiler - Damaged - Replace
6	2nd wheel set	Alloy rim set - complete - Scratched - Loss in value
7	Misc.	Inspection / maintenance - Due - Perform
8	Door - rear right side	Door - Dent / paintcoat damage - Repair and paint
9	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint
10	Vehicle glazing	Windscreen with lane departure assistant (Mit Rissbildung) - Stone chips - Replace
11	Front bumper	Front bumper - Deformed - Replace

Wear and tear

No.	Component group	Description
1	Body	Body - Scratch(es) - No deduction
2	Interior	Interior - Abrasion - No deduction
3	Seat - front	Backrest cover - left side - Abrasion - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
-----	----------

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 28 Apr 2025

Protocol number: 39496125

Delivery date: 28 Apr 2025



Auto Plus

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 94H	Goodyear	Winter tyres	7mm - 7mm	o.k.	
2	225/50 R17 94H	Goodyear	Winter tyres	7mm - 7mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	265/30 R20 94Y	Dunlop	Summer tyres	5mm - 5mm	o.k.	
2	265/30 R20 94Y	Dunlop	Summer tyres	6mm - 6mm	o.k.	

Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					08/2025

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 28 Apr 2025

Protocol number: 39496125

Delivery date: 28 Apr 2025



Auto Plus

Vehicle details

Manufacturer	Audi	Inspection condition	Sufficient
Type / Model	A5 Sportback	Mileage (Read)	102,051 km
Vehicle Identification number	WAUZZZF54LA020770	First registration	13 Jul 2020

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front




Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior




Figure 6: Interior



Figure 7: Interior



Figure 8: Interior




Figure 9: Interior



Figure 10: Misc.




Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 28 Apr 2025
Protocol number: 39496125
Delivery date: 28 Apr 2025




Figure 19: Misc.

Pictures of damage




Damage #1: Door - front right side: Door - dent(s) - Smooth repair work



Damage #1: Door - front right side: Door - dent(s) - Smooth repair work




Damage #2: Mudguard - left side: Mudguard - left side - Scratched... Smart repair



Damage #2: Mudguard - left side: Mudguard - left side - Scratched - Smart repair



Damage #4: Wing mirror - right side: Mirror housing - Damaged - Replace



Damage #4: Wing mirror - right side: Mirror housing - Damag... - Replace



Damage #4: Wing mirror - right side: Mirror housing - Damaged - Replace




Damage #4: Wing mirror - right side: Mirror housing - Damaged - Replace



Damage #5: Front bumper: Spoiler - Damaged - Replace



Damage #4: Wing mirror - right side: Mirror housing - Damag... - Replace



Damage #5: Front bumper: Spoiler - Damaged - Replace



Damage #6: 2nd wheel set: Alloy rim set - complete - Scratch... - Loss in value



Damage #6: 2nd wheel set: Alloy rim set - complete - Scratched - Loss in value



Damage #6: 2nd wheel set: Alloy rim set - complete - Scratched - Loss in value



Damage #6: 2nd wheel set: Alloy rim set - complete - Scratched - Loss in value



Damage #6: 2nd wheel set: Alloy rim set - complete - Scratch... - Loss in value



Damage #6: 2nd wheel set: Alloy rim set - complete - Scratch... - Loss in value



Damage #6: 2nd wheel set: Alloy rim set - complete - Scratch... - Loss in value



Damage #6: 2nd wheel set: Alloy rim set - complete - Scratched - Loss in value



Damage #7: Misc.: Inspection / maintenance - Due - Perform




Damage #8: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint




Damage #8: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage #8: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint




Damage #8: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint




Damage #8: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage #9: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage #9: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage #9: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage #10: Vehicle glazing: Windscreen with lane departure assistant (Mit Rissbildung) - Stone chips - Replace



Damage #10: Vehicle glazing: Windscreen with lane departure assistant (Mit Rissbildung) - Stone chips - Replace



Damage #10: Vehicle glazing: Windscreen with lane departure assistant (Mit Rissbildung) - Stone chips - Replace



Damage #11: Front bumper: Front bumper - Deformed - Replace



Damage #11: Front bumper: Front bumper - Deformed - Replace



Damage #11: Front bumper: Front bumper - Deformed - Replace



Damage #11: Front bumper: Front bumper - Deformed - Replace