



WAUZZZFY5N2010658

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	118,518 km
Manufacturer	Audi	Next maintenance in	1,500 km
Type / Model	Q5 50 TFSI e	Main inspection (Report not on hand)	12/2024
Vehicle Identification number	WAUZZZFY5N2010658	Power / Engine displacement	195 kW / 1,984 ccm
First registration	8 Dec 2021	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Hybr.B/E ext. edition	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - Due - Perform
2	Boot lid / rear door	Rear spoiler - Scratch(es) - Paint
3	Door - rear left side	Door - Scratch(es) - Paint
4	Door - rear right side	Door - Scratch(es) - Paint
5	Rear bumper	Rear bumper - Scratch(es) - Paint
6	Front bumper	Front bumper - Scratch(es) - Paint
7	Door - front left side	Door - Scratch(es) - Paint
8	Door - front right side	Door - Scratch(es) - Paint
9	Vehicle glazing	Windscreen with lane departure assistant - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Interior	Interior - Abrasion - No deduction
2	Body	Body - Scratch(es) - No deduction

Missing parts

Missing part

Previous damages

No.	Previous damage
1	Front, Provided by user / customer

Detected repainting

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 29 Apr 2025

Protocol number: 39500964

Delivery date: 29 Apr 2025



Auto Plus

No.	Location
1	Roof, Mudguard - right side, Bonnet, Professionally carried out

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	235/65 R17 104H	Pirelli	Winter tyres	5mm - 5mm	o.k.	o.k.
2	235/65 R17 104H	Pirelli	Winter tyres	5mm - 5mm	o.k.	o.k.

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	235/60 R18 103V	Michelin	Summer tyres	3mm - 3mm	o.k.	o.k.
2	235/60 R18 103V	Michelin	Summer tyres	5mm - 5mm	o.k.	o.k.

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, N.i.O

Fahrzeug war zum Zeitpunkt der Besichtigung verschmutzt, weitere Beschädigungen können nicht ausgeschlossen werden.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 29 Apr 2025
Protocol number: 39500964
Delivery date: 29 Apr 2025



Vehicle details

Manufacturer	Audi	Inspection condition	conditional: light/moisture/dirt
Type / Model	Q5 50 TFSI e	Mileage (Read)	118,518 km
Vehicle Identification number	WAUZZZFY5N2010658	First registration	8 Dec 2021

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.

Pictures of damage



Damage #2: Boot lid / rear door: Rear spoiler - Scratch(es) - Paint



Damage #2: Boot lid / rear door: Rear spoiler - Scratch(es) - Paint



Damage #2: Boot lid / rear door: Rear spoiler - Scratch(es) - Paint



Damage #3: Door - rear left side: Door - Scratch(es) - Paint



Damage #3: Door - rear left side: Door - Scratch(es) - Paint



Damage #3: Door - rear left side: Door - Scratch(es) - Paint



Damage #3: Door - rear left side: Door - Scratch(es) - Paint




Damage #4: Door - rear right side: Door - Scratch(es) - Paint



Damage #4: Door - rear right side: Door - Scratch(es) - Paint



Damage #4: Door - rear right side: Door - Scratch(es) - Paint



Damage #5: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage #5: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage #5: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage #5: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage #5: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage #6: Front bumper: Front bumper - Scratch(es) - Paint



Damage #6: Front bumper: Front bumper - Scratch(es) - Paint



Damage #7: Door - front left side: Door - Scratch(es) - Paint



Damage #7: Door - front left side: Door - Scratch(es) - Paint



Damage #7: Door - front left side: Door - Scratch(es) - Paint




Damage #8: Door - front right side: Door - Scratch(es) - Paint



Damage #8: Door - front right side: Door - Scratch(es) - Paint



Damage #9: Vehicle glazing: Windscreen with lane departure assistant - Broken / torn - Replace



Damage #9: Vehicle glazing: Windscreen with lane departure assistant - Broken / torn - Replace