



WAUZZZFZXPP069543

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	33,104 km
Manufacturer	Audi	Next maintenance in	2 Monat(e)
Type / Model	Q4 40 e-tron	Main inspection (Taken from ZBI)	07/2026
Vehicle Identification number	WAUZZZFZXPP069543	Power / Engine displacement	70 kW
First registration	24 Jul 2023	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Electric	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Documents	Service book - No evidence
2	Wheel / tyres	Alloy rim - front right side - Scratched - No deduction
3	Trim / covers	Sill - front right side - dent(s) - Replace
4	Engine	Engine cover - top / cover - Damage caused by marten / rodent - Replace
5	Front bumper	Spoiler - Scratch(es) - Loss in value
6	Rear bumper	Rear bumper - Scratched - Smart repair

Wear and tear

No.	Component group	Description
1	Body	Body (Steinschläge) - Scratch(es) - No deduction
2	Interior	Interior - Abrasion - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	235/55 R19 101T	Bridgestone	Winter tyres	5mm - 5mm	o.k.	
2	235/55 R19 101T	Bridgestone	Winter tyres	5mm - 5mm	o.k.	

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 16 May 2025
Protocol number: 39749977
Delivery date: 16 May 2025



Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	255/50 R19 103T	Hankook	Summer tyres	5mm - 5mm	o.k.	
2	255/50 R19 103T	Hankook	Summer tyres	5mm - 5mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 16 May 2025
Protocol number: 39749977
Delivery date: 16 May 2025



Vehicle details

Manufacturer	Audi	Inspection condition	Sufficient
Type / Model	Q4 40 e-tron	Mileage (Read)	33,104 km
Vehicle Identification number	WAUZZZFZXPP069543	First registration	24 Jul 2023

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient for the assessment of the vehicle.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior




Figure 10: Misc.




Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 16 May 2025
Protocol number: 39749977
Delivery date: 16 May 2025



Figure 19: Misc.



Figure 20: Misc.

Pictures of damage




Damage #2: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction




Damage #2: Wheel / tyres: Alloy rim - front right side - Scratched - No deduction




Damage #3: Trim / covers: Sill - front right side - dent(s) - Replace



Damage #3: Trim / covers: Sill - front right side - dent(s) - Replace



Damage #4: Engine: Engine cover - top / cover - Damage caused by marten / rodent - Replace



Damage #4: Engine: Engine cover - top / cover - Damage caused by marten / rodent - Replace



Damage #5: Front bumper: Spoiler - Scratch(es) - Loss in value



Damage #5: Front bumper: Spoiler - Scratch(es) - Loss in value



Damage #6: Rear bumper: Rear bumper - Scratched - Smart repair



Damage #6: Rear bumper: Rear bumper - Scratched - Smart repair



Damage #6: Rear bumper: Rear bumper - Scratched - Smart repair