



WBA6K51030FJ86093

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	134,044 km
Manufacturer	BMW	Next maintenance in	9,000 km
Type / Model	330i	Main inspection (Report on hand)	05/2025
Vehicle Identification number	WBA6K51030FJ86093	Power / Engine displacement	190 kW / 1,998 ccm
First registration	5 Jun 2020	Upholstery/Colour	/
Last maintenance	04/2025, 131,890 km	Paintwork	
Fuel type	Petrol	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	2nd wheel set	2 tyres - Expired - No deduction
2	Wheel / tyres	Alloy rim - rear left side - Scratched - No deduction
3	Wheel / tyres	Alloy rim - front right side - Scratched - No deduction
4	Equipment	Vehicle key (Fehlt) - No deduction
5	Misc.	Main inspection - Due - Replace
6	2nd wheel set	1 alloy rim - Scratched - Loss in value
7	Rear bumper	Rear bumper - Scratched - Smart repair
8	Side panel - rear left side	Sill - Scratched - Smart repair
9	Sill - left side	Trim - Scratched - Smart repair
10	Sill - right side	Trim - Scratched - Smart repair
11	Roof	Roof rail - right side - Scratched - Smart repair
12	Vehicle glazing	Windscreen - Damaged - Replace
13	Front bumper	Front bumper - Deformed - Replace

Wear and tear

No.	Component group	Description
1	Interior	Interior - Abrasion - No deduction
2	Body	Body (Steinschläge) - Scratch(es) - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 6 May 2025
Protocol number: 39579892
Delivery date: 6 May 2025



Auto Plus

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/45 R18 95V	Pirelli	Winter tyres	7mm - 7mm	o.k.	
2	225/45 R18 95V	Pirelli	Winter tyres	2mm - 2mm	Not o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/45 R18 95Y	Michelin	Summer tyres	6mm - 6mm	o.k.	
2	255/40 R18 95Y	Goodyear	Summer tyres	5mm - 5mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und

Richtigkeit der angezeigten Ausstattung.

Techn. Änderungen vorbehalten

Das Fahrzeug weist dem Alter, der Laufleistung und dem

Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 6 May 2025
Protocol number: 39579892
Delivery date: 6 May 2025



Auto Plus

Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	330i	Mileage (Read)	134,044 km
Vehicle Identification number	WBA6K51030FJ86093	First registration	5 Jun 2020

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient for the assessment of the vehicle.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Waldorf

Inspection date: 6 May 2025
Protocol number: 39579892
Delivery date: 6 May 2025



Figure 7: Interior



Figure 8: Interior




Figure 9: Interior



Figure 10: Misc.




Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.






Figure 22: Misc.


Pictures of damage




Damage #2: Wheel / tyres: Alloy rim - rear left side - Scratched - ...
deduction



Damage #2: Wheel / tyres: Alloy rim - rear left side - Scratched
- No deduction




Damage #3: Wheel / tyres: Alloy rim - front right side - Scratched -
No deduction



Damage #3: Wheel / tyres: Alloy rim - front right side -
Scratched - No deduction



Damage #6: 2nd wheel set: 1 alloy rim - Scratched - Loss in value



Damage #7: Rear bumper: Rear bumper - Scratched - Smart
repair



Damage #7: Rear bumper: Rear bumper - Scratched - Smart repair



Damage #7: Rear bumper: Rear bumper - Scratched - Smart repair



Damage #7: Rear bumper: Rear bumper - Scratched - Smart repair



Damage #8: Side panel - rear left side: Sill - Scratched - Smart repair



Damage #8: Side panel - rear left side: Sill - Scratched - Smart repair



Damage #9: Sill - left side: Trim - Scratched - Smart repair



Damage #9: Sill - left side: Trim - Scratched - Smart repair




Damage #10: Sill - right side: Trim - Scratched - Smart repair




Damage #10: Sill - right side: Trim - Scratched - Smart repair



Damage #11: Roof: Roof rail - right side - Scratched - Smart repair



Damage #12: Vehicle glazing: Windscreen - Damaged - Replace



Damage #13: Front bumper: Front bumper - Deformed - Replace



Damage #13: Front bumper: Front bumper - Deformed - Replace



Damage #13: Front bumper: Front bumper - Deformed - Replace



Damage #13: Front bumper: Front bumper - Deformed - Replace