



WAUZZZFYXL2114222

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	63,982 km
Manufacturer	Audi	Next maintenance in	4,500 km
Type / Model	Q5 50 TFSI e	Main inspection (Read from ZBI)	12/2025
Vehicle Identification number	WAUZZZFYXL2114222	Power / Engine displacement	185 kW / 1,984 ccm
First registration	23 Oct 2020	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Hybr.B/E ext. edition	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Documents	Service book (Wartungsnachweise fehlen) - No deduction
2	Documents	Log book (Fehlt) - Replace
3	Documents	Main inspection certificate (Fehlt) - Replace
4	Door - rear left side	Door - dent(s) - Smooth repair work
5	Side panel - rear left side	Wheel well extension - Scratched - Smart repair
6	Side panel - rear right side	Wheel well extension - Scratched - Smart repair
7	Interior	Boot cover / roller cover - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Door - front left side	Door handle - outside - Scratch(es) - No deduction
2	Body	Body (Steinschläge) - Scratch(es) - No deduction
3	Vehicle glazing	Windscreen (Steinschläge) - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	255/40 R21 102Y	Pirelli	Summer tyres	5mm - 5mm	o.k.	
2	255/40 R21 102Y	Pirelli	Summer tyres	8mm - 8mm	o.k.	

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 25 Apr 2025
Protocol number: 39467331
Delivery date: 25 Apr 2025



Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	235/65 R17 108H	Goodyear	Winter tyres	7mm - 7mm	o.k.	
2	235/65 R17 108H	Goodyear	Winter tyres	5mm - 5mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

Fahrzeug war zum Zeitpunkt der Besichtigung regennass, weitere Beschädigungen können nicht ausgeschlossen werden.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 25 Apr 2025

Protocol number: 39467331

Delivery date: 25 Apr 2025



Auto Plus

Vehicle details

Manufacturer	Audi	Inspection condition	conditional: light/moisture/dirt
Type / Model	Q5 50 TFSI e	Mileage (Read)	63,982 km
Vehicle Identification number	WAUZZZFYXL2114222	First registration	23 Oct 2020

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

A proper visual inspection of the paintwork and the bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. At the time of the inspection, the condition could not be ensured for an adequate assessment. The expert therefore recommends a further inspection to reduce the prognosis risk.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.

TÜV SÜD Auto Plus GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH
69190 Walldorf

Inspection date: 25 Apr 2025
Protocol number: 39467331
Delivery date: 25 Apr 2025




Figure 25: Misc.

Pictures of damage



Damage #4: Door - rear left side: Door - dent(s) - Smooth repair work



Damage #4: Door - rear left side: Door - dent(s) - Smooth repair work



Damage #5: Side panel - rear left side: Wheel well extension - Scratched - Smart repair



Damage #5: Side panel - rear left side: Wheel well extension - Scratched - Smart repair



Damage #6: Side panel - rear right side: Wheel well extension - Scratched - Smart repair



Damage #6: Side panel - rear right side: Wheel well extension - Scratched - Smart repair



Damage #7: Interior: Boot cover / roller cover - Broken / torn - Replace



Damage #7: Interior: Boot cover / roller cover - Broken / torn - Replace