



WBA6N31070FL38162

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	35,737 km
Manufacturer	BMW	Next maintenance in	0 Monat(e)
Type / Model	330e	Main inspection (Report on hand)	06/2026
Vehicle Identification number	WBA6N31070FL38162	Power / Engine displacement	135 kW / 1,998 ccm
First registration	21 May 2021	Upholstery/Colour	/
Last maintenance	06/2024, 28,187 km	Paintwork	
Fuel type		Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Side panel - rear right side	Sill - Dent / paintcoat damage - Smart repair
2	Misc.	Inspection / maintenance - Due - Replace
3	Rear bumper	Rear bumper (Stark) - Scratched - Replace

Wear and tear

No.	Component group	Description
1	Body	Body (Steinschläge) - Scratch(es) - No deduction
2	Vehicle glazing	Windscreen (Steinschläge) - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98H	Pirelli	Winter tyres	5mm - 5mm	o.k.	
2	225/50 R17 98H	Pirelli	Winter tyres	5mm - 5mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/45 R18 95Y	Pirelli	Summer tyres	5mm - 5mm	o.k.	
2	255/40 R18 99Y	Pirelli	Summer tyres	4mm - 4mm	o.k.	

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 7 May 2025
Protocol number: 39596436
Delivery date: 7 May 2025



The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und

Richtigkeit der angezeigten Ausstattung.

Techn. Änderungen vorbehalten

Das Fahrzeug weist dem Alter, der Laufleistung und dem

Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 7 May 2025
Protocol number: 39596436
Delivery date: 7 May 2025



Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	330e	Mileage (Read)	35,737 km
Vehicle Identification number	WBA6N31070FL38162	First registration	21 May 2021

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient for the assessment of the vehicle.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.




Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.


Pictures of damage



Damage #1: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage #1: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage #1: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage #2: Misc.: Inspection / maintenance - Due - Replace



Damage #3: Rear bumper: Rear bumper (Stark) - Scratched - Replace



Damage #3: Rear bumper: Rear bumper (Stark) - Scratched - Replace