



TRUZZZFV0M1005161

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	73,269 km
Manufacturer	Audi	Next maintenance in	0 km
Type / Model	TT Coupé	Main inspection (Report on hand)	06/2026
Vehicle Identification number	TRUZZZFV0M1005161	Power / Engine displacement	180 kW / 1,984 ccm
First registration	23 Apr 2021	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Petrol	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Roof	Roof rail - right side - Scratch(es) - Cover / polish
2	Side panel - rear right side	Side panel - Scratch(es) - Cover / polish
3	Trim / covers	Door trim - front right side - Deformed - Loss in value
4	Side panel - rear left side	Side panel - Scratch(es) - Smart repair
5	Misc.	Inspection / maintenance - Due - Perform
6	2nd wheel set	Alloy rim set - complete - Scratched - Loss in value
7	Sill - left side	Trim - Scratched - Replace
8	Mudguard - right side	Mudguard - right side - Dent / paintcoat damage - Repair and paint
9	Front bumper	Front bumper - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Door - front right side	Door edge - Scratched - No deduction
2	Body	Body - Stone chips - No deduction
3	Body	Body - Scratch(es) - No deduction
4	Interior	Interior - Abrasion - No deduction
5	Vehicle glazing	Windscreen - Stone chips - No deduction

Missing parts

Missing part

Previous damages

No.	Previous damage
1	Underbody, Provided by user / customer



Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98V	Michelin	Winter tyres	6mm - 6mm	o.k.	
2	225/50 R17 98V	Michelin	Winter tyres	6mm - 6mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	245/40 R18 93Y	Goodyear	Summer tyres	6mm - 6mm	o.k.	
2	245/40 R18 97Y	Pirelli	Summer tyres	5mm - 5mm	o.k.	

Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					05/2026

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 7 May 2025
Protocol number: 39597151
Delivery date: 7 May 2025



Vehicle details

Manufacturer	Audi	Inspection condition	Sufficient
Type / Model	TT Coupé	Mileage (Read)	73,269 km
Vehicle Identification number	TRUZZZFV0M1005161	First registration	23 Apr 2021

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient for the assessment of the vehicle.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior




Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.

Pictures of damage



Damage #1: Roof: Roof rail - right side - Scratch(es) - Cover / polish




Damage #1: Roof: Roof rail - right side - Scratch(es) - Cover / polish



Damage #1: Roof: Roof rail - right side - Scratch(es) - Cover / polish



Damage #2: Side panel - rear right side: Side panel - Scratch(es) - Cover / polish



Damage #2: Side panel - rear right side: Side panel - Scratch(es) - Cover / polish



Damage #2: Side panel - rear right side: Side panel - Scratch(es) - Cover / polish



Damage #3: Trim / covers: Door trim - front right side - Deformed - Loss in value



Damage #3: Trim / covers: Door trim - front right side - Deformed - Loss in value



Damage #4: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage #4: Side panel - rear left side: Side panel - Scratch(...) - Smart repair



Damage #6: 2nd wheel set: Alloy rim set - complete - Scratched - Loss in value



Damage #6: 2nd wheel set: Alloy rim set - complete - Scratch... - Loss in value



Damage #6: 2nd wheel set: Alloy rim set - complete - Scratched - Loss in value



Damage #6: 2nd wheel set: Alloy rim set - complete - Scratch... - Loss in value



Damage #7: Sill - left side: Trim - Scratched - Replace



Damage #7: Sill - left side: Trim - Scratched - Replace



Damage #7: Sill - left side: Trim - Scratched - Replace




Damage #7: Sill - left side: Trim - Scratched - Replace



Damage #8: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage #8: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage #8: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage #9: Front bumper: Front bumper - Scratched - Repair and paint



Damage #9: Front bumper: Front bumper - Scratched - Repair and paint



Damage #9: Front bumper: Front bumper - Scratched - Repair and paint

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 7 May 2025

Protocol number: 39597151

Delivery date: 7 May 2025



Damage #9: Front bumper: Front bumper - Scratched - Repair and paint