



Brand:	BMW	Mileage(km):	219625
Model:	X1	Number of doors:	5
Model type:	sDrive20i Business	Vehicle length (cm):	
License plate:	29SXR8	Vehicle width (cm):	
Report code:	4445	Vehicle height (cm):	
Chassis number:	WBAVL91090VT74445	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Rear
First int. reg.:	23/12/2011	Power(kw):	135
First NL reg.:	23/12/2011	Transmission:	Automatic
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears:	8
Weight (kg)(kg):	1585	Displacement(cc):	1997
Empty weight(kg):	1485	Number of cylinders:	4
Wheelbase (cm)(cm):	276	Fuel type:	Petrol
Top speed (km/h):	205	Fuel tank capacity:	
Cons. in the city (l/100 km):	9.4	EU category:	Euro 5
Cons. outside the city (l/100 km):	5.8	Energy label:	C
Average consumption (l/100 km):	7.1	NL Tax Rate %:	
Acceleration (s):	7.7	CO2 (g/km):	165
Cargo space (l):	1585	Nb. of Axles:	2
Perm. max weight (kg):	2060	APK date:	23/12/2025

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Panoramic roof (electrical) | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> Halogen headlights | <input checked="" type="checkbox"/> Climate control |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Climate control (digital) |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Climate control (L/R separated) |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Sport seats |
| <input checked="" type="checkbox"/> Start/stop system | <input checked="" type="checkbox"/> Radio/CD player | <input checked="" type="checkbox"/> Extendable passenger seat |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Radio/CD/MP3 player | <input checked="" type="checkbox"/> Extendable driver's seat |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> Bluetooth car kit (retro fit) | <input checked="" type="checkbox"/> Leather sports steering wheel |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Cruise control | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Roof rail (silver) | <input checked="" type="checkbox"/> Sports package (interior) | |
| <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Black top interior | |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Steel	225/50 R17	Pirelli	5
Tire left rear	Winter	Steel	225/50 R17	Pirelli	5
Tire right front	Winter	Steel	225/50 R17	Pirelli	5
Tire right rear	Winter	Steel	225/50 R17	Pirelli	5
Tire left front	Summer	Alloy	225/45 R19	Continental	6
Tire left rear	Summer	Alloy	225/45 R19	Continental	4
Tire right front	Summer	Alloy	225/45 R19	Continental	6
Tire right rear	Summer	Alloy	225/45 R19	Continental	4

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	03/02/2025	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	218253	<input checked="" type="checkbox"/> Vehicle special usage (None)

⚠ Cleaning

Clean inside (Interior is clean)

Clean outside

🔧 Damages

⊕ Not acceptable



Front right rim - Scratch



Rear right rim - Scratch



Rear left rim - Scratch



Front left rim - Scratch



Bonnet - Paint repair



Front bumper - Break



Left sill - Scratch



Rear bumper - Scratch



Front bumper - Scratch

🔧 Damages

⊕ Acceptable

⚙ Extra options





