



Brand:	Dacia	Mileage(km):	135219
Model:	Logan mcv	Number of doors:	5
Model type:	0.9 TCe Prestige	Vehicle length (cm):	
License plate:	7TKL88	Vehicle width (cm):	
Report code:	5503	Vehicle height (cm):	
Chassis number:	UU17SDAA550525503	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	13/03/2014	Power(kw):	66
First NL reg.:	13/03/2014	Transmission	Manual
Color:	Blue <input type="checkbox"/> Metallic	Number of gears	5
Weight (kg)(kg):	1113	Displacement(cc):	898
Empty weight(kg):	1013	Number of cylinders:	3
Wheelbase (cm)(cm):	263	Fuel type:	Petrol
Top speed (km/h):	175	Fuel tank capacity:	
Cons. in the city (l/100 km):	6.4	EU category:	Euro 5
Cons. outside the city (l/100 km):	4.3	Energy label:	B
Average consumption (l/100 km):	5	NL Tax Rate %:	25
Acceleration (s):	11.1	CO2 (g/km):	116
Cargo space (l):	1113	Nb. of Axles:	2
Perm. max weight (kg):	1620	APK date:	13/03/2026

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Bluetooth streaming |
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> Roof rail (silver) | <input checked="" type="checkbox"/> Bluetooth car kit |
| <input checked="" type="checkbox"/> Towing hook | <input checked="" type="checkbox"/> Halogen headlights | <input checked="" type="checkbox"/> Radio |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Cruise control |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Towbar with fixed ball | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Rear-seat folding (equal parts) | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Start/stop system | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Aux connection | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> iPod connection | |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> USB connection | |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	185/65 R15	Vredestein	6
Tire left rear	Summer	Alloy	185/65 R15	Vredestein	5
Tire right front	Summer	Alloy	185/65 R15	Vredestein	6
Tire right rear	Summer	Alloy	185/65 R15	Vredestein	4

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	21/02/2025	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	132887	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Cleaning)

🔧 Damages

⊗ Not acceptable



Front bumper - Scratch



Bonnet - Restyle dent



Rear left door - Paint repair



Front left door - Restyle dent



Rear bumper - Paint repair



Rear bumper - Dent



Tailgate/ lid - Paint repair



Roof - Restyle dent



Rear right door - Paint repair

🔧 Damages

⊗ Acceptable

⚙️ Extra options





