



WAUZZZGE8MB034682

Vehicle details

Operator		Inspection condition	conditional: light/ moisture/dirt
License number		Mileage (Read)	67,723 km
Manufacturer	Audi	Next maintenance in	28,500 km
Type / Model	e-tron 50 quattro Sports Utility Vehicle5-türig 0 ccm 313 PS / 230 KW Elektrisch Automatik		
Vehicle Identification number	WAUZZZGE8MB034682	Main inspection	
		Power / Engine displacement	230 kW / 1 ccm
First registration	29 Apr 2021	Upholstery/Colour	Cloth / Anthracite-Grey
Last maintenance		Paintwork	Black
Fuel type	Electric	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - front right side (Materialabtrag optisch gering) - Scratched - No deduction
2	Trim / covers	Roof lining - Soiled - Clean
3	Documents	Log book (fehlt) - Replace
4	Side panel - rear right side	Sill - Scratch(es) - Smart repair
5	Front bumper	Spoiler - Scratched - Repair and paint
6	Misc.	Main inspection - No evidence - Perform
7	Rear bumper	Rear bumper - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Body	Body (Kratzer,Dellen) - Stone chips - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	



Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	255/55 R19 111V	Dunlop	Winter tyres	5mm - 5mm	Not o.k.	Not o.k.
2	255/55 R19 111V	Dunlop	Winter tyres	4mm - 4mm	Not o.k.	Not o.k.

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	255/50 R19 111H	Bridgestone	Summer tyres	5mm - 5mm	Not o.k.	o.k.
2	255/50 R19 111H	Bridgestone	Summer tyres	5mm - 5mm	Not o.k.	o.k.

Replacement

Type	Tyre size	Manufacturer	Type of tyre	Tread depth	Expiration date
Tirefit					05/2026

The wear and tear condition and possible damages to the tyres are considered in the value.

Equipment

Equipment

Description
Air conditioning
Navigation unit with map view
Radio

Comments

Der montierte Winterradsatz ist nicht Bestandteil des Auslieferungsumfangs

Keine Gewähr auf Vollständigkeit und

Richtigkeit der angezeigten Ausstattung.

Techn. Änderungen vorbehalten.

Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.



Vehicle details

Manufacturer	Audi	Inspection condition	conditional: light/moisture/dirt
Type / Model	e-tron 50 quattro Sports Utility Vehicle5-türig 0 ccm 313 PS / 230 KW Elektrisch Automatik	Mileage (Read)	67,723 km
Vehicle Identification number	WAUZZZGE8MB034682	First registration	29 Apr 2021

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior




Figure 10: Interior



Figure 11: Interior



Figure 12: Interior




Figure 13: Interior




Figure 14: VIN



Figure 15: Accessories



Figure 16: Accessories



Figure 17: Accessories



Figure 18: Accessories



Figure 19: Documents



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.

Pictures of damage



Damage #1: Wheel / tyres: Alloy rim - front right side
(Materialabtrag optisch gering) - Scratched - No deduction




Damage #1: Wheel / tyres: Alloy rim - front right side
(Materialabtrag optisch gering) - Scratched - No deduction




Damage #2: Trim / covers: Roof lining - Soiled - Clean



Damage #2: Trim / covers: Roof lining - Soiled - Clean



Damage #4: Side panel - rear right side: Sill - Scratch(es) - Smart repair




Damage #4: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage #5: Front bumper: Spoiler - Scratched - Repair and paint




Damage #5: Front bumper: Spoiler - Scratched - Repair and paint



Damage #7: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #7: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #7: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage #7: Rear bumper: Rear bumper - Scratched - Repair and paint

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 23 May 2025
Protocol number: 39870247



Damage #7: Rear bumper: Rear bumper - Scratched - Repair and paint