



WAUZZZFZ3RP079009

Vehicle details

Operator		Inspection condition	conditional: light/ moisture/dirt
License number		Mileage (Read)	19,534 km
Manufacturer	Audi	Next maintenance in	12 Monat(e)
Type / Model	Q4 Sportback e-tron 45 e-tron Sports Utility Vehicle5-türig 0 ccm 286 PS / 210 KW Elektrisch Automatik		
Vehicle Identification number	WAUZZZFZ3RP079009	Main inspection	
		Power / Engine displacement	/ 1 ccm
First registration	1 Jul 2024	Upholstery/Colour	Cloth / leather combination / Black
Last maintenance		Paintwork	Grey
Fuel type	Electric	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	2nd wheel set	2nd wheel set (fehlt) - No deduction

Wear and tear

No.	Component group	Description
	The vehicle shows traces of wear and tear corresponding to its age and purpose	

Missing parts

Missing part

Detected repainting

No.	Location
	None detectable

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	235/45 R21 101T	Pirelli	Summer tyres	6mm - 6mm	o.k.	o.k.
2	255/40 R21 102T	Pirelli	Summer tyres	6mm - 6mm	o.k.	o.k.

The wear and tear condition and possible damages to the tyres are considered in the value.

TÜV SÜD Auto Partner GmbH
Gutenbergstrasse 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 13 May 2025
Protocol number: 39962751



Equipment

Equipment

Description
Automatic air conditioning
Navigation unit with map view
Radio DAB

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten.
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.

elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.



Vehicle details

Manufacturer	Audi	Inspection condition	conditional: light/ moisture/dirt
Type / Model	Q4 Sportback e-tron 45 e-tron Sports Utility Vehicle5-türig 0 ccm 286 PS / 210 KW Elektrisch Automatik	Mileage (Read)	19,534 km
Vehicle Identification number	WAUZZZFZ3RP079009	First registration	1 Jul 2024

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior




Figure 10: Interior



Figure 11: Interior




Figure 12: VIN



Figure 13: Accessories



Figure 14: Accessories




Figure 15: Documents



Figure 16: Mounted tyres




Figure 17: Misc.




Figure 18: Misc.

TÜV SÜD Auto Partner GmbH
Gutenbergstrasse 13
70771 Leinfelden-Echterdingen

Inspection location
Autokontor Bayern GmbH
Windecker Straße 2
61137 Schöneck

Inspection date: 13 May 2025
Protocol number: 39962751




Figure 19: Misc.