



WBA11DZ080FL99150

Vehicle details

Operator		Inspection condition	conditional: light/moisture/dirt
License number		Mileage (Read)	59,291 km
Manufacturer	BMW	Next maintenance in	-2,800 km
Type / Model	320d	Main inspection (Taken from ZBI)	10/2024
Vehicle Identification number	WBA11DZ080FL99150	Power / Engine displacement	140 kW / 1,995 ccm
First registration	20 Oct 2021	Upholstery/Colour	/
Last maintenance	01/2024, 37,287 km	Paintwork	
Fuel type	Hybrid Diesel / E	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Door - rear right side	Door - Scratch(es) - Cover / polish
2	Braking system	Brake fluid - Due - Replace
3	Misc.	Main inspection - Due - Replace
4	Rear bumper	Rear bumper - Scratched - Smart repair
5	Wheel / tyres	Alloy rim - rear right side - Scratched - Loss in value
6	Misc.	Inspection / maintenance - Due - Replace
7	Front bumper	Front bumper - Scratched - Smart repair

Wear and tear

No.	Component group	Description
1	Interior	Interior - Abrasion - No deduction
2	Body	Body (Steinschläge) - Scratch(es) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Door - front left side	Door edge - Scratched - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	



Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/45 R18 95Y	Pirelli	Summer tyres	4mm - 4mm	o.k.	
2	225/45 R18 95Y	Pirelli	Summer tyres	4mm - 4mm	o.k.	

Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98H	Pirelli	Winter tyres	6mm - 6mm	o.k.	
2	225/50 R17 98H	Pirelli	Winter tyres	6mm - 6mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

Fahrzeug war zum Zeitpunkt der Besichtigung verschmutzt, weitere Beschädigungen können nicht ausgeschlossen werden

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 20 May 2025

Protocol number: 39800796

Delivery date: 20 May 2025



Vehicle details

Manufacturer	BMW	Inspection condition	conditional: light/moisture/dirt
Type / Model	320d	Mileage (Read)	59,291 km
Vehicle Identification number	WBA11DZ080FL99150	First registration	20 Oct 2021

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.




Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.

Pictures of damage



Damage #1: Door - rear right side: Door - Scratch(es) - Cover / polish



Damage #1: Door - rear right side: Door - Scratch(es) - Cover / polish



Damage #2: Braking system: Brake fluid - Due - Replace



Damage #4: Rear bumper: Rear bumper - Scratched - Smart repair



Damage #4: Rear bumper: Rear bumper - Scratched - Smart repair




Damage #4: Rear bumper: Rear bumper - Scratched - Smart repair




Damage #5: Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value




Damage #5: Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value



Damage #6: Misc.: Inspection / maintenance - Due - Replace



Damage #7: Front bumper: Front bumper - Scratched - Smart repair



Damage #7: Front bumper: Front bumper - Scratched - Smart repair