



WBA5P51030FK28016

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	28,619 km
Manufacturer	BMW	Next maintenance in	30,000 km
Type / Model	330e	Main inspection (Report not on hand)	10/2025
Vehicle Identification number	WBA5P51030FK28016	Power / Engine displacement	135 kW / 1,998 ccm
First registration	6 Oct 2020	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Hybr.B/E ext. edition	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - rear right side - Scratched
2	Wheel / tyres	Alloy rim - rear left side - Scratched
3	Documents	Main inspection certificate (Fehlt) - Replace
4	Equipment	Vehicle key with remote control (Fehlt) - Replace
5	Mudguard - right side	Mudguard - right side - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
The vehicle shows traces of wear and tear corresponding to its age and purpose		

Missing parts

Missing part

Previous damages

No.	Previous damage
1	Front, Provided by user / customer

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98H	Pirelli	Winter tyres	7mm - 7mm	o.k.	
2	225/50 R17 98H	Pirelli	Winter tyres	5mm - 5mm	o.k.	

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 14 May 2025
Protocol number: 39731509
Delivery date: 14 May 2025



Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/50 R17 98Y	Bridgestone	Summer tyres	4mm - 4mm	o.k.	
2	225/50 R17 98Y	Bridgestone	Summer tyres	4mm - 4mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 14 May 2025
Protocol number: 39731509
Delivery date: 14 May 2025



Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	330e	Mileage (Read)	28,619 km
Vehicle Identification number	WBA5P51030FK28016	First registration	6 Oct 2020

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient for the assessment of the vehicle.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior




Figure 10: Misc.



Figure 11: Misc.



Figure 12: Misc.



Figure 13: Misc.




Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.

Pictures of damage



Damage #1: Wheel / tyres: Alloy rim - rear right side - Scratched



Damage #1: Wheel / tyres: Alloy rim - rear right side - Scratched



Damage #2: Wheel / tyres: Alloy rim - rear left side - Scratched



Damage #2: Wheel / tyres: Alloy rim - rear left side - Scratched



Damage #5: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage #5: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 14 May 2025
Protocol number: 39731509
Delivery date: 14 May 2025



Damage #5: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint