



WBA31EE0105Z34314

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	20,595 km
Manufacturer	BMW	Next maintenance in	12,000 km
Type / Model	X1 sDrive20i	Main inspection (Taken from ZBI)	04/2027
Vehicle Identification number	WBA31EE0105Z34314	Power / Engine displacement	115 kW / 1,499 ccm
First registration	16 Apr 2024	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Hybrid Petrol / E	Gearbox	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Door - front left side	Door - dent(s) - Smooth repair work
2	Side panel - rear right side	Side panel - dent(s) - Smooth repair work
3	Rear bumper	Rear bumper - Scratched - Paint
4	Sill - right side	Trim - Scratched - Replace
5	Door - rear right side	Door - Scratched - Paint
6	Side panel - rear left side	Side panel - Scratched - Paint

Wear and tear

No.	Component group	Description
1	Body	Body - Scratch(es) - No deduction
2	Interior	Interior - Abrasion - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/55 R18 102Y	Nexen	Summer tyres	5mm - 5mm	o.k.	
2	225/55 R18 102Y	Nexen	Summer tyres	6mm - 6mm	o.k.	

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 27 May 2025
Protocol number: 39917225
Delivery date: 27 May 2025



Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/55 R18 102V	Pirelli	Winter tyres	5mm - 5mm	o.k.	
2	225/55 R18 102V	Pirelli	Winter tyres	6mm - 6mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 27 May 2025

Protocol number: 39917225

Delivery date: 27 May 2025



Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	X1 sDrive20i	Mileage (Read)	20,595 km
Vehicle Identification number	WBA31EE0105Z34314	First registration	16 Apr 2024

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient for the assessment of the vehicle.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior




Figure 6: Interior



Figure 7: Interior




Figure 8: Interior




Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.




Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 27 May 2025

Protocol number: 39917225

Delivery date: 27 May 2025



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.


Pictures of damage



Damage #1: Door - front left side: Door - dent(s) - Smooth repair work



Damage #1: Door - front left side: Door - dent(s) - Smooth repair work



Damage #2: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage #2: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage #3: Rear bumper: Rear bumper - Scratched - Paint



Damage #3: Rear bumper: Rear bumper - Scratched - Paint



Damage #4: Sill - right side: Trim - Scratched - Replace



Damage #4: Sill - right side: Trim - Scratched - Replace



Damage #4: Sill - right side: Trim - Scratched - Replace



Damage #5: Door - rear right side: Door - Scratched - Paint



Damage #5: Door - rear right side: Door - Scratched - Paint



Damage #6: Side panel - rear left side: Side panel - Scratched - Paint

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
Allane Mobility Consulting
GmbH

69190 Walldorf

Inspection date: 27 May 2025
Protocol number: 39917225
Delivery date: 27 May 2025



Damage #6: Side panel - rear left side: Side panel - Scratched - Paint