



WBA7M910805T25890

Vehicle details

Operator		Inspection condition	Sufficient
License number		Mileage (Read)	137,409 km
Manufacturer	BMW	Next maintenance in	15,000 km
Type / Model	118d	Main inspection (Report on hand)	02/2026
Vehicle Identification number	WBA7M910805T25890	Power / Engine displacement	110 kW / 1,995 ccm
First registration	18 Feb 2021	Upholstery/Colour	/
Last maintenance		Paintwork	
Fuel type	Diesel	Gearbox	Manual

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Door - rear right side	Door - dent(s) - Smooth repair work
2	Door - front left side	Door - dent(s) - Smooth repair work
3	Rear bumper	Rear bumper - Scratched - Smart repair
4	Boot lid / rear door	Boot lid - Scratched - Paint
5	Door - front right side	Door - Scratched - Paint
6	Front bumper	Front bumper - Deformed - Replace

Wear and tear

No.	Component group	Description
1	Body	Body - Scratch(es) - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction
3	Interior	Interior - Abrasion - No deduction

Missing parts

Missing part

Detected repainting

No.	Location
None detectable	

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	205/55 R16 91V	Pirelli	Summer tyres	6mm - 6mm	o.k.	
2	205/55 R16 91V	Pirelli	Summer tyres	8mm - 8mm	o.k.	

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 26 May 2025
Protocol number: 39893412
Delivery date: 26 May 2025



Additional tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	205/55 R16 91H	Continental	Winter tyres	6mm - 6mm	o.k.	
2	205/55 R16 91H	Continental	Winter tyres	7mm - 7mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Comments

Keine Gewähr auf Vollständigkeit und
Richtigkeit der angezeigten Ausstattung.
Techn. Änderungen vorbehalten
Das Fahrzeug weist dem Alter, der Laufleistung und dem
Einsatzzweck entsprechende Gebrauchsspuren auf.
elektr. Komponenten geprüft, i. O.

Lackwerte geprüft, i. O.

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 26 May 2025
Protocol number: 39893412
Delivery date: 26 May 2025



Vehicle details

Manufacturer	BMW	Inspection condition	Sufficient
Type / Model	118d	Mileage (Read)	137,409 km
Vehicle Identification number	WBA7M910805T25890	First registration	18 Feb 2021

Vehicle identification:

The vehicle identification number (VIN) was read and the undersigned verified that it matched the documents submitted during the inspection.

Inspection conditions:

The inspection conditions were sufficient for the assessment of the vehicle.

General condition:

The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear



Figure 5: Interior



Figure 6: Interior

TÜV SÜD Auto Partner GmbH
Gutenbergstr. 13
70771 Leinfelden-Echterdingen

Inspection location
SAP SE
Dietmar-Hopp-Allee 16
69190 Walldorf

Inspection date: 26 May 2025
Protocol number: 39893412
Delivery date: 26 May 2025



Figure 7: Interior



Figure 8: Interior



Figure 9: Interior



Figure 10: Misc.



Figure 11: Misc.




Figure 12: Misc.



Figure 13: Misc.



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.

Pictures of damage




Damage #1: Door - rear right side: Door - dent(s) - Smooth repair work




Damage #1: Door - rear right side: Door - dent(s) - Smooth repair work



Damage #2: Door - front left side: Door - dent(s) - Smooth repair work



Damage #2: Door - front left side: Door - dent(s) - Smooth repair work



Damage #3: Rear bumper: Rear bumper - Scratched - Smart repair work



Damage #3: Rear bumper: Rear bumper - Scratched - Smart repair work



Damage #4: Boot lid / rear door: Boot lid - Scratched - Paint



Damage #4: Boot lid / rear door: Boot lid - Scratched - Paint



Damage #5: Door - front right side: Door - Scratched - Paint



Damage #5: Door - front right side: Door - Scratched - Paint



Damage #5: Door - front right side: Door - Scratched - Paint



Damage #6: Front bumper: Front bumper - Deformed - Replace



Damage #6: Front bumper: Front bumper - Deformed - Replace



Damage #6: Front bumper: Front bumper - Deformed - Replace